




DELHI POLLUTION CONTROL COMMITTEE
4th & 5th FLOOR, ISBT BUILDING, KASHMERE GATE, DELHI-06
(visit us at : <http://dpcc.delhigovt.nic.in>)

F. No. DPCC/ Committee II (b) /15th Meeting / 2016/ 6529-33 **Dated: 17-11-16**

Subject: Minutes of the **15th Meeting of the Committee for II (b) Category Cases** headed by Member Secretary, DPCC, held on **04.11.2016**, in the Conference Room of DPCC at ISBT Building Kashmer Gate , Delhi -06.

Please find enclosed herewith the Minutes of the **15th Meeting** of the aforementioned Committee, held on **04.11.2016**, in the Conference Room of DPCC at ISBT Building Kashmer Gate , Delhi -06.

Concerned Cells are required to take necessary action as per the decisions taken by the Committee.



(D.K.Singh)

Sr. Env. Engineer(CDC)
Consent Management Cell- II

1. Member Secretary, DPCC.
2. SEEs (CMC I/II/III/IV/V).
3. Environmental Engineers (CMC I/II/III/IV/V).

Copy for information to:

1. PS to Chairman, DPCC ,for kind information of Chairman, DPCC please.
2. In-Charge, Enquiry Counter & IT Cell, for placing the aforementioned minutes of the meeting of the Committee on the website of DPCC .


(D.K.Singh)

Sr. Env. Engineer(CDC)
Consent Management Cell- II

Minutes of the 15th Meeting of the Committee for II (b) Category cases, headed by Member Secretary, DPCC and constituted vide office order dated 12.04.2016, for deciding Consent under the Air & Water Acts and Authorization under the Hazardous & Other Wastes / Plastic Waste Rules, held on 04.11.2016, in the conference room of DPCC, at 5th Floor, ISBT Building, Kashmere Gate, Delhi-06.

Attendance Sheet is enclosed as Annexure "A".

Following are the Minutes of the Meeting:-

In case of the units of redevelopment areas which have applied for Consent/Authorization to DPCC, the Committee decided to ask the units to submit Certificate, in original, from Industries Department, Govt. of NCT of Delhi regarding location of the unit within the boundary of the notified redevelopment areas clearly mentioning the name & address of the unit in the said certificate. Copy of such letters issued to the units may also be sent to the Industries Department.

List of units in redevelopment areas which have applied for Consent/Authorization to DPCC be sent to the Commissioner, Industries Department, Govt. of NCT of Delhi for verification / confirmation of the location of the unit within the boundary of the notified redevelopment areas and subsequently on monthly basis by the concerned CMC i.e. CMC-IV dealing with the matter / issues related to redevelopment areas.

It was informed to the Committee by concerned Engineers of CMC-I that in compliance of the decision taken by the Committee in its meeting held on 30.09.2016, letter was sent to the Department of Industries on 26.10.2016 for confirming the location of the unit w.r.t. redevelopment areas of Shahdara, Mandoli, Jawahar Nagar & Karawal Nagar and the list of the such industries were also sent along with the said letter. Matter of New Mandoli, Redevelopment Area is pending before Hon'ble National Green Tribunal (NGT) and also Public Grievances Commission (PGC), Govt. of NCT of Delhi. To expedite the disposal of consent applications of New Mandoli Redevelopment Area, joint inspection by Industries Department, SDM and DPCC shall be conducted to ascertain location of the industries within the boundary of the New Mandoli Redevelopment Area.

Agenda Item No 1: 107 Pending Cases of Consent to Establish/Operate /Renewal of the period 01.04.2016 to 31.10.2016

Decisions were taken online in individual cases and list of 33 no. of Consent to Establish cases are at Annexure I and list of 74 no. of Consent to Operate / Renewal cases are at Annexure II.

Following Table Agenda Items were taken by the Committee with the permission of chair:-

Table Agenda Item No 1: 03 Pending Cases of Consent to Operate of CMC-IV

Decisions were taken online in these cases and are given at Annexure III.

Table Agenda Item No 2: Case of M/s Skygourmet Catering Pvt. Ltd., IGI Airport Complex, Near Centure Hotel, Delhi-110037 (ID No. 10i99 CTO(R) Dated 20.02.2015 for the activity of Flight Catering.

The Case was briefed by the concerned engineers of CMC-II.

The unit is engaged in the activity of Flight Catering and have installed Sewage Treatment Plant (STP) for the treatment of waste water generated from the unit. Unit is also having three oil fired boilers and two D.G. Sets of capacity of 725 KVA each having individual acoustic enclosure and adequate stack height.

Earlier, provisional Consent to Operate (Renewal) was issued on 10.05.2016 for six months for submission of permission of DJB for extraction of ground water as decided by concerned Committee in its meeting held on 26.02.2016. Directions for closure issued to the unit on 17.10.2014 were also revoked.

Contd.2...

[Handwritten signatures and initials at the bottom of the page]

In response to the said letter Dated 10.05.2016, the unit has informed that they have obtained the Delhi Jal Board payment receipts towards usage charges on the industries for operating the bore-wells for extraction of ground water which is as per the DJB circular Dated 06.04.2015 and Dated 30.09.2015 and also submitted copy of acknowledgement Dated 03.07.2014 towards voluntary disclosure of the bore-well by the unit. Unit has also submitted Effluent analysis report for STP Dated 05.09.2016, Stack Monitoring Report for boilers Dated 09.09.2016 and Noise Monitoring Report for D.G. Sets Dated 06.09.2016 showing the unit is meeting the prescribed standards.

In view of the decision taken by DPCC and communicated vide letter Dated 28.07.2016 issued to Chief Executive Officer, Delhi Jal Board & Secretary (Revenue) cum Divisional Commissioner, Govt. of NCT of Delhi [with copy to Member (Water), Delhi Jal Board and all Dy. Commissioners of 11 Districts], the Committee decided not to hold consent applications on the issue of ground water extraction / use of ground water / outside source for water supply (tankers) and decide the cases from the pollution control point of view so that provisions of the pollution control laws can be implemented / enforced in NCT of Delhi.

In view of the above, Committee decided to grant Consent to Operate(Renewal) to the unit.


Since decisions were taken online in individual cases by the Committee and tabular list is generated through software including decisions taken in each case, there is no need of signature of the members of the Committee on such lists (**Annexure I, II & III**). The concerned Cell may take necessary action w.r.t. decisions taken without waiting for the minutes of the meeting.

In future, if any case is falling in the chronology of the period selected for meeting however not appearing in the agenda item generated through existing software, such cases be brought before the Committee for taking offline decision.

If there is any case left out of the aforementioned period, the same shall be put up administratively for further necessary action.

The meeting ended with a vote of thanks to the Chair.



(S.M. Ali)
Member Secretary, DPCC


(D.K. Singh)
SEE, CMC-II


(M. Arif)
SEE, CMC- V


(P.S.Panka)
EE, CMC- IV



(B.L.Chawla)
SEE, CMC-I


(Satender Kumar)
SEE, CMC-III


(D.K. Srivastava)
EE, CMC-III


(M.S. Rawat)
EE, CMC-V


(N.K.Joshi)
EE, CMC-III


(Sanjay Vatts)
EE, CMC-II












(Shyam Sunder)
EE, CMC-I


(Ramesh Chandra)
EE, CMC-II


(Amit Chaudhary)
EE, CMC-V


(Sunil Kumar)
EE, CMC-IV

Attendance Sheet for 15th Meeting of the Committee constituted vide office order Dated 12.04.2016 and headed by Member Secretary, DPCC, for deciding Consent under the Air & Water Acts and Authorization under the Hazardous and Other Wastes /Plastic Waste Rules of the units under **Category II (b)**, for the **Pending Consent to Establish /Operate /Renewal cases of the period 01.04.2016 to 31.10.2016**, held on **04.11.2016** in the Conference Room of DPCC at ISBT Building, Kashmere Gate, Delhi.

S.No.	Name	Designation	Signature
1.	Sh. S. M. Ali	Member Secretary, DPCC	
2.	Sh. D.K. Singh	SEE(CDC)(CMC II), DPCC	
3.	Sh. M. Arif	SEE(CDC) (CMC V), DPCC	
4.	Sh. P. S. Pankaj	EE, Incharge CMC IV, DPCC	
5.	Sh. B. L. Chawla	SEE(CDC)(CMC I),DPCC	
6.	Sh. Satender Kumar	SEE(CDC) (CMC III), DPCC	
7.	Sh. D. K. Srivastava	EE(CDC) (CMC III), DPCC	
8.	Sh. N.K.Joshi	EE(CDC) (CMC III), DPCC	
9.	Sh. M. S. Rawat	EE(CDC) (CMC V), DPCC	
10.	Sh. Sanjay Vatts	EE(CDC) (CMC II), DPCC	
11.	Sh. Shyam Sunder	EE(CDC) (CMC I), DPCC	
12.	Sh. Ramesh Chandra	EE(CDC) (CMC II), DPCC	
13.	Sh. Amit Chaudhary	EE(CDC) (CMC V), DPCC	
14.	Sh. Sunil Kumar	EE(CDC) (CMC IV), DPCC	
15.	Sh. K. Kumar	EE(CDC) (CMC IV), DPCC	- Absent -



CONSENT MANAGEMENT

Decisions taken by the Committee for II(b) Category cases headed by Member Secretary DPCC in its 15th meeting on 04.11.2016 w.r.t. Agenda Item No 1 -- 33 Pending Cases of Consent to Establish of the period 01.04.2016 to 31.10.2016 (Annexure I).

S. No.	Industry Name	Address	Date of Application	Application No	Activities / Product	Consent Application [CTE / CTO / CTO(R)]	Category (SPI/Non SPI)	Authorization Status (Granted/Applied - Fresh/Renewal)	Brief of Case	Status of Test Report(s)	Remarks (Whether unit fulfills all conditions for grant of Consent / Authorisation)	Decison
1	KAVERI WASH	H-1351 DSIIDC INDUSTRIAL AREA NARELA	04-04-2016	DPCC/EC/2/1/2016/14186	Washing of Readymae garments (With oil fired boiler) Readymade Garment (with Washing) with Boiler Spray Painting, Paint Baking, Paint Stripping	Orange Establish	Non-SPI		Status of Pollution Control system/Devices: 1. ETP- Proposed (10KLD) 2. ECS- N/A 3. D.G. set- No Status of Ground Water Extraction:No 1. Water consumption: 9800 L/day. a) Source of water: Other source (copy of Other source not bill submitted) Plot Area: 350 sq.mt. Status of Inspection: Yes Inspection was conducted on 11.01.16 by the officials of DPCC and inspection findings are as follows: 1. Unit found operating & engaged in the activity of Dyeing & washing of jeans w/o consent from DPCC. 2. No ETP installed. waste water is being dicahrged directly into sewer w/o any treatment. 3. Two boilers (1T/hr, 500 kg/hr) exists. One boiler (500kg/hr) was in use & coal, wood used as fuel causing air pollution. No ECS installed. 4. HWM rules not complied with. 5. Ground water extracted through borewell w/o permission from DJB/CGWA. Show Cause Notice u/s 31 (A) of Air Act, 33(A) of Water Act & u/s 5 of EPA issued on 24.02.2016.	Test Reports: Air (Emission)-N/A Water (Effluent)-N/A Noise Test Report- N/A	24-06-2016 - Remarks/ATR on 03-11-2016 Compliance of closure directions not received from concerned authorities. Another reply received on 17.10.2016 wherein unit has stated that they are doing only washing of ready made garment and not doing any dyeing, ETP already installed and runing properly, Coal fired boiler is converted into oil fired and trying to get test report from DPCC lab. After getting report consent to operate shall be submitted soon. Further requested for revocation of closure directions. Inspection is yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection is yet to be conducted. As unit has failed to apply for Consent to Operate after giving sufficient time,	04-11-2016 Expedite inspection.

									Modified directions u/s 31 (A) of Air act, u/s 33 (A) of Water act and u/s 5 of EPA giving 45 days time to comply with the pollution control norms & to apply for consent & authorisation issued on 29.04.2016		proposal of Directions for closure is already put up in common file.	
2	BOHEMIA (A UNIT OF HIGH HAT FASHIONS)	N-1, IIND FLOOR, GREATER KAILASH, PART-I	05-04-2016	DPCC/EC/2/1/2016/14192	RESTAURANT (48 SEATS). Restaurants/Eating Houses / Dhabas and other such establishments (with minimum Seating Capacity of 36)/Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of One Tonne/Day or more)/ Banquet Halls/Party-Lawns (with minimum Floor Area of 100m ²) connected to public/municipal/DJB sewer	Orange Establish	Non-SPI		Status of Pollution Control System (1)ETP / Oil & Grease Trap cum Settling tank - Proposed (2)ECS - N/A (3)D.G.Set: 62.5 KVA (Proposed) Water Consumption - 3500 ltrs /day Source of water - DJB (Bill provided) Status of Ground Water extraction : Nil MCD & Delhi Police License valid upto 31.03.2018 for 48 seats Complaint received from Sh. G Singh against Restaurants operating in N Block Market, Greater Kailash, Part-I, New Delhi-48 through PGMS bearing ID No. 201541074, accordingly an inspection of the unit was carried out by representatives of DPCC on 08.10.2015 and following were observed: - Unit found operating with activity of Restaurant cum Bar with 98 seats. - Unit has installed only Oil & Grease trap but not	N/A	29-06-2016 During inspection of the unit on 08.10.2015 it was found that unit having 98 seats. However, unit has applied for Consent to Operate for 48 seats. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Inspection is yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 File has been put up administratively and as decided in file direction u/s 33 (A) of Water Act and 31 (A) of Air Act was issued to unit on 19.08.2016 as unit has not submitted any reply/representation w.r.t SCN and also not applied for CTO. Unit has submitted its reply/representation on 02.09.2016 w.r.t direction issued to	04-11-2016 Expedite inspection.

									installed Effluent Treatment Plant (ETP). - Channelization system in kitchen with inadequate stack height. - 1 DG set of capacity 125 KVA with Inadequate stack height. - Source of water is DJB.Copy of Bill obtained. - Unit has not provided MCD health & Delhi Police License. Show Cause Notice under Water & Air Act issued to the unit on 28.10.2015. Reply not received from unit so far. Reminder Show Cause Notice under Water & Air Act issued to the unit on 09.02.2016. No reply received however they have applied for Consent to establish on 05.04.2016. Unit has applied for Consent to Establish for the activity of Restaurant (48 seats) on 05.04.2016. However, unit has not submitted application for Consent to Operate, so far. Unit has not submitted any reply to any of the two notices w.r.t. deficiencies observed in the inspection. During inspection of the unit on 08.10.2015 it was found that unit having 98 seats. However, unit has applied for Consent to Operate for 48 seats.		unit on 19.08.2016 stating that : 1. They have 48 seating restaurant and have Consent to Establish certificate for that, MCD & Delhi Police license copy attached. 2. They have already ordered the ETP and installation process is in process (copy enclosed). 3. They will raise the stack height of channelization system in kitchen upto permissible limit. 4. They will raise the stack height of DG Set upto permissible limit and will also apply for stack monitoring certificate through DPCC. Unit has requested 30 day time to apply for CTO and to complete all prescribed formalities adhering to all norms mentioned as per DPCC.	
3	GAURVA UNIVERSAL WASH	F-200, SECTOR-5, DSIIDC, BAWANA INDUSTRIAL AREA	27-04-2016	DPCC/EC/2/1/2016/14467	JOB WORK OF WASHING OF READYMADE GARMENTS (WITH OIL FIRED BOILER). Readymade Garment (with Washing) with Boiler	Orange Establish	Non-SPI		Status of Pollution Control system/Devices: 1. ETP- Proposed (10KLD) 2. ECS- N/A 3. D.G. set- No Status of Ground Water Extraction:No 1. Water consumption: 10000 L/day. a) Source of water: Outside source (copy of Outside source bill submitted) Plot Area: 100 sq.mt. Status of Inspection: Yes Inspection was conducted	Test Reports: Air (Emission)-N/A Water (Effluent)-N/A Noise Test Report- N/A	24-06-2016 - Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection is yet to be conducted. As unit has failed to apply for Consent to Operate after giving sufficient time. Directions for closure was issued on 29.04.2016. Proposal of Compliance of	04-11-2016 Expedite inspection.

									on 14.01.16 by the officials of DPCC and inspection findings are as follows: 1. Unit found operating & engaged in the activity of Dyeing & washing of jeans without consent from DPCC. 2. No ETP installed. Waste water is being dicahrged directly into sewer without any treatment. 3. One wood fired boiler exists causing air pollution. No ECS installed. 4. HWM rules are not complied with. 5. One borewell connection exists without permission from DJB/CGWA. Show Cause Notice u/s 31 (A) of Air Act, 33(A) of Water Act & u/s 5 of EPA issued on 24.02.2016. Directions for closure u/s 31(A) of Air act, u/s 33 (A) of Water act and u/s 5 of EPA issued on 29.04.2016 Reply received on 17.05.2016 stated that they are not doing Dying and doing washing of ready made garments. Coal fired boiler is converted into oil fired. Requested for revocation of closure directions and 45 to 60 days time short to submit ETP report, stack monitoring report etc.to fullll fill other documents.		closure directions from concerned authorities is already put up in common file.	
4	PASCOS	B1/I-3, MOHAN CO- OPERATIVE INDUSTRIAL ESTATE, MAIN MATHURA ROAD,	11-06-2016		sales, service, spares, parking, repairs etc Automobile Servicing and Repair Station with Washing Activity	Orange Establish	Non-SPI		The unit has applied for Consent to Establish for the Activity of Automobile Service Station with washing through online mode however has not submitted the Hard Copy of the Consent application and other required documents to DPCC so far.	N.A	24-06-2016 Unit has not submitted the Hard Copy of the Consent application and other required documents to DPCC and therefore a letter may be issued seeking the same within 15 Days. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 File under submission.	04-11-2016 Expedite inspection.

											Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 As decided, a letter was issued to unit on 02.08.2016 to submit hard copies of consent application along with required documents within 15 days.	
5	WEDDING OPERA (A UNIT OF S G HOSPITALITY)	B 9 LAWRENCE ROAD INDL AREA	27-06-2016	DPCC/EC/2/1/2016/15214	BANQUET HALL Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Establish	Non-SPI		Status of Pollution Control System (1)ETP ---- N/A (2)ECS - N/A (3)D.G.Set: ...125 KVA (Proposed) Status of Ground Water extraction : Nil Source of Water: 20 KLD from DJB Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No Unit has submitted the following: 1. Copy of License dt 20.06.2016 issued by Department of Labour. 2. Copy of receipt to apply for MCD License dt. 23.06.2016. 3. Copy of License dt 27.05.2016 issued by the Controller legal Metrology.	N/A	20-07-2016 . Remarks/ATR on 03-11-2016 A public complaint PGMS was earlier received against the unit and now the unit has installed ETP.Inspection of the unit conducted as approved in the file put up in response to a show cause notice issued to the unit. The unit was found in operation. ETP has also been installed and the same was found in operational status. unit has two DG sets of 90 and 40 kva both are with acoustic enclosure and with adequate stack height. Channelization system with kitchen is also provided by the unit above the roof level. Recommendation / Action Taken Details (EE/AEE) on 06-10-2016 The file was put up administratively and inspection of the unit has been approved in the file. The inspection has been conducted. Recommendation / Action Taken Details (EE/AEE) on 14-09-2016 File is under submission for	04-11-2016 Consent to Establish granted with the condition that the unit shall apply for Consent to Operate within 03 months.

											decision wrt Directions u/s 33 (A) of Water Act and u/s 31(A) of Air Act.	
6	RAJINDER SERVICE STATION	2, SHAM NATH MARG	30-06-2016	DPCC/EC/2/1/2016/15378	PETROL PUMP CUM SERVICE STATION OF CARS. Automobile Fuel Outlet (with Automobile Servicing, Washing, Repairing and Painting)	Orange Establish	Non-SPI	HWM Application No. 1 Application Date 30-06-2016 Authorisation Status Pending	Status of Pollution Control system/Devices: 1. ETP- proposed 2. ECS- N/A 3. D.G. set- 1x82.5 KVA Plot Area- 1124.12 sq mt Date of commencement- 01.01.1976 Status of Ground Water Extraction: No 1. Water consumption: 3000 L/day. a) Source of water: DJB (copy of DJB water bill submitted) Status of Inspection: No Unit has applied online and not submitted the following documents: (i)Sanctioned building plan(DDA/MCD) (ii) Approved layout plan (DDA/MCD) (iii) Allotment letter/dealership agreement is valid as on date (iv) Letter from oil company that dealership agreement is valid as on date (v) Authority letter, in original, regarding filling/signing of consent/authorization application.	Effluent analysis report - N/A Air (Emission)-N/A Noise Test Report- N/A	20-07-2016 - Remarks /ATR on 04-11-2016 Letter issued on 21.09.2016 to submit the deficient documents mentioned in the receipt of CTE application within 15 days. No reply received till date. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Letter issued. Reply awaited. Remarks /ATR on 30-08-2016 -	04-11-2016 Expedite inspection. Issue reminder.
7	GIAN FOUNDRY WORKS	B-1 TO B-5, MAYAPURI INDUSTRIAL AREA, PHASE- II	21-07-2016	DPCC/EC/2/1/2016/15550	C.I. CASTING THROUGH PIT FURNACE Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Establish	Non-SPI		Source of Water: Outside (copy of bill not provided) Water Consumption:100 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP ---- N/A (2)ECS - Proposed (3)D.G.Set: ...N/A... -A complaint received in office and as approved,an inspection is conducted by DPCC officials on 10.02.2016 and unit found operating without taking consent and without ESC over cupola furnace. -A show cause notice was issued to the unit on 13.05.2016. -Unit failed to submit reply		30-08-2016 . Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 No reply received w.r.t our latter dated 26.09.2016. Recommendation / Action Taken Details (EE/AEE) on 27-09-2016 -A letter issued to the unit on 26.09.2016 regarding informing about the date of commissioning of the unit and also either to submit one documentary proof or consent fee w.e.f. 01.06.1991 as per office order dated 20.05.2016.	04-11-2016 Consent to Establish granted. Subsequently, inspection be conducted.

									w.r.t show cause notice. -Accordingly, a closure direction was issued to the unit on 19.07.2016. -Unit submit its reply w.r.t closure direction and submit its application for consent to establish and rectify the deficiencies observed during inspection and requested to revoke the closure direction. - As decided, a temporary revocation was issued to the unit on 22.08.2016 for 30 days for submitting consent to operate application with all requisite documents.		
8	UNITED FABRICATORS	B-1 TO B-5, MAYAPURI INDUSTRIAL AREA, PHASE-II	25-07-2016	DPCC/EC/2/1/2016/15588	C.I. CASTING THROUGH PIT FURNACE WITH MACHINING(LIGHT ENGINEERING WORKS). Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Establish	Non-SPI		Source of Water:Outside (copy of bill not provided) Water Consumption: 200 Litres/ Day Status of Ground Water extraction : No Status of Pollution Control System (1)ETP ---- N/A (2)ECS - Proposed (3)D.G.Set: ...N/A... -A complaint revived in office and as approved an inspection was conducted by DPCC officials on 29.06.2016 and found operating without consent. -Accordingly, a show cause notice was issued to the unit on 05.07.2016. -Unit submit its reply on 25.07.2016 and informed that uni has applied fr consent to establish on 25.07.2016.	30-08-2016 Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 -Unit submits its reply on 17.10.2016 along with an undertaking and stated that M/s United Fabricators engaged in manufacturing of casting through pit furnace with machining (Light Engineering Works) earlier they were engaged in assembling work (Light Engineering Works) only but they have take over pit furnace from Happy Metal (which were operated at the same premises since 07.03.2016) on dated 21.07.2016. -Also as informed that copy of rent agreement enclosed but it is not provided. Recommendation / Action Taken Details (EE/AEE) on 27-09-2016 -A letter issued to	04-11-2016 Inspection be conducted.

											the unit on 26.09.2016 regarding informing about the date of commissioning of the unit and also either to submit one documentary proof or consent fee w.e.f. 01.06.1991 as per office order dated 20.05.2016.	
9	CHANSON HOSPITALITY PVT. LTD	30/23/2/2 MIN ON MAIN ROHTAK ROAD, NANGLOI JAT	27-07-2016	DPCC/EC/2/1/2016/15610	BANQUET HALL. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Establish	Non-SPI		Source of Water: Tanker (copy of bill not provided) Water Consumption:15000 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP - Working (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	Water Effluent: Effluent analysis report dated 23-08-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes	29-08-2016 Copy of water tanker bill not provided. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Consent to operate may be granted. Also closure direction be revoked. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 - As decided in the meeting file be put up administratively and the brief of the unit mentioned below: - A complaint received against the unit on 06.07.2015. accordingly it has been decided to inspect the unit. - An inspection was carried out on 11.12.2015 and following observations were made: -CTE obtained not applied for CTO yet. -ETP installed but found in defunct condition. -Waste water directly being discharged in to sewer. -No channelization done in the kitchen. -In kitchen area lot of bad smell observed. - D.G Set have acoustic enclosure but inadequate	04-11-2016 Consent to Establish granted.

										stack height. - One borewell observed no permission shown. -No MCD & Delhi Police License shown for operation of banquet hall. -Only banqueting is done. No restaurant exists. -A Show Cause Notice u/s 31 (A) & 33 (A) issued to the unit on 25.01.2016. - Unit failed to submit any reply w.r.t above mentioned SCN. -As decided, closure direction was issued to the unit on 24.05.2016. -CTE may be granted also, closure direction be revoked temporarily for 45 days to apply CTO application.	
10	CHANSON BANQUET	17A, SHIVAJI MARG, NAJAFGARH ROAD INDUSTRIAL AREA	08-08-2016	DPCC/EC/2/1/2016/15699	BANQUET HALL. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Establish	Non-SPI		Source of Water: Tanker (Copy of bill not provided) Water Consumption: 15000 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP -- Working (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	30-08-2016 . Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 -Consent to establish and consent to operate may be granted. Also, closure direction be revoked. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 -As decided in the meeting file put up administratively and the brief about the unit is mentioned below. -As per the order of Honourable NGT in the matter of Manoj Mishra V/s Union of India and Ors in O.A No. 06 of 2012 and O.A No. 300 of 2013 has ordered on 11.08.2015 that the industries which are operating in any of	04-11-2016 Consent to Establish granted.

the 28 industrial clustered without consent of DPCC should be served with notice of closure.

- As inspection of the unit was carried out on 28.05.2015 and various deficiencies were observed.
- A Show Cause Notice u/s 31 (A) & 33(a) was issued to the unit on 08.09.2015 and also a letter to concerned Dy. commissioner w.r.t extraction of ground water on 08.09.2015.
- An inspection was carried out on 03.02.2016 and following observations were made:
 - Unit operating since January, 2015.
 - Not applied for CTE & CTO yet.
 - No channelisation done in the kitchen.
 - ETP installed but was totally defunct. only structure found laying at roof of the building.
 - Hundred percent waste water is being discharged in to sewer without treatment.
 - D.G Set has inadequate stack height.
 - Unit has one borewell without permission.
- A reminder issued to Dy. commissioner w.r.t extraction of ground water on 15.12.2015.
- A closure direction u/s 31(A) & 33(A) was issued to the unit on 26.05.2016.
- CTE may be granted and also, closure direction be revoked temporarily

											for 45 days to apply CTO application.	
11	A AND V ZIPPERS PVT. LTD.	E-46/3, OKHLA INDUSTRIAL AREA, PHASE-II	11-08-2016	DPCC/EC/2/1/2016/15779	BASE KITCHEN(NO SEATING ARRANGEMENT AND NO BY PRODUCTS). Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Establish	Non-SPI		Status of Pollution Control System (1)ETP - Yes (a) Effluent analysis report dated 01-07-2016 issued by SHRIRAM INSTITUTE submitted. Effluent Test Report within Limit - No. (2)ECS - N/A (3)D.G.Set- Yes (a) The unit has 2 D.G. Set(s) of 125 KVA. Noise monitoring report dated 27-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise monitoring report within Limit - Yes Status of Ground Water extraction : Nil Water consumption- 4800 litres/day , Source- DJB (Bill enclosed)	Effluent analysis report dated 01-07-2016 issued by SHRIRAM INSTITUTE submitted. Effluent Test Report within Limit - No . The unit has 2 D.G. Set(s) of 125 KVA. Noise monitoring report dated 27-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise monitoring report within Limit - Yes	30-08-2016 Unit has also applied for CTO on 11.08.2016 Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 As decided by the Committee, Show Cause Notice u/s 33(A) of Water Act issued on 22.09.2016. The unit has submitted replies on 29.09.2016 & 21.10.2016 w.r.t. Show Cause Notice dated 22.09.2016 along with Effluent Analysis Report from DPCC Laboratory. The unit has informed that they have installed ETP which is regularly operated and maintained by their operator with proper care. The unit has also informed that they would follow all the norms of DPCC and requested to withdraw the show cause notice. Effluent Analysis Report from DPCC Laboratory dated 10.10.2016, submitted by the Unit along with its Letter dated 21.10.2016, reveals that the parameters are within the prescribed limit. As decided, inspection of the unit was carried out by the Officials / Representatives of DPCC on 03.11.2016 and following were observed- - Unit found in operation & engaged in the activity of Base	04-11-2016 Consent to Establish granted.

											Kitchen. - Unit has provided Oil & grease Trap at ground floor. - Unit has installed ETP (Operational) consists of Aeration tank, Equalization tank, Filters but capacity / size of the ETP is need to be increased & also requires to provide sludge drying bed. - Channelization system with hood are provided with 4 burners / range, however hood not provided with 2 burners / range & also stack height upto roof level.	
12	NANDA MINERALS	D-106, KESHOPUR INDUSTRIAL AREA, VIKASPURI	12-08-2016	DPCC/EC/2/1/2016/15820	MINERAL WATER. Mineralised Water/Water Treatment Plant	Orange Establish	Non-SPI		Source of water: Through tanker Category-II (copy of bill not provided) Water consumption: 4000 litre/day Status of Ground Water extraction:Nil Status of Pollution Control System (1)ETP ---- proposed (2)ECS - N/A (3)D.G.Set : Nil As per approval unit was inspected by DPCC, Officials on 17.08.2015 and during inspection following were observed: (a) Unit found operational and engaged in the activity of manufacturing and trading of RO Water. (b) One borewell found exist, however, one is in defunct state. (c) No D.G. Set found installed at the premises. (d) One RO plant found in the premises use for bottling plant. (e) Rain water harvesting pit is used to store the rain water and RO reject water. -As per inspection findings a Show Cause Notice for closure u/s 31(A) of Air Act & u/s 33(A) of Water Act was issued to the unit on 08.09.2015 & also letter was issued to concerned Dy. Commissioner w.r.t. extraction of ground water	31-08-2016 Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 As per decision an inspection of the unit has been carried out by DPCC, Officials on 16.09.2016. during inspection following observations were made: -unit found operational and engaged in the activity of mfg. of mineral water. -No. D.G Set found installed. -Reverse Osmosis (RO) plant found installed at the first floor of the building & same found operational. -A Show cause notice for closure may be issued to the unit to install sequential RO Plant using High quality membrane and zero discharge. If, unit	04-11-2016 Implement the decision dated 30.09.2016.	

									on 08.09.2015. -Unit has submitted its reply along with an undertaking on 28.09.2015 and informed that the activity of the unit falls under Orange category and shall apply for Consent to Establish and Operate and requesting to grant 30 days time to comply with all the pollution norms. -Again a Modified Direction u/s 33 (A) of water act & 31 (A) of Air act sent to the unit on 04.12.2015 & also reminder issued to concerned Dy. Commissioner w.r.t. extraction of ground water.		fails to do so consent application be infructuous and also closure direction may be issued.	
13	SOMPAN PRODUCTS PVT. LTD.	A-33, NARAINA INDUSTRIAL AREA, PHASE-I	12-08-2016	DPCC/EC/2/1/2016/15836	MANUFACTURING OF CHEWING TOBACCO. Tobbaco Products without Raw Tobacco Processing	Orange Establish	Non-SPI		Source of Water: Delhi Jal Boared connection (copy of bill not provided) Water Consumption: 1000 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP ---- N/A (2)ECS - N/A (3)D.G.Set Noise Report : 1 D.G. Set(s) of 500 KVA -A complaint received in this office, an inspection was conducted by DPCC officials on 08.08.2016 and unit found operating without taking consent and ducting is not provided. -For further necessary action file is under process.	Noise Emission: The unit has 1 D.G. Set(s) of 500 KVA. Noise monitoring report dated 24-08-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	30-08-2016 Copy of water bill not provided. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 No reply received from Department of Food Safety Govt. of NCT of Delhi w.r.t to our latter dated 27.09.2016. Recommendation / Action Taken Details (EE/AEE) on 27-09-2016 -A letter issued to the Department of Food Safety Govt. of NCT of Delhi on 27.09.2016 regarding permissibly of the activity of Manufacturing of Chewing Tobacco w.r.t. notification dated 13.04.2016 and court orders etc., if any.	04-11-2016 Issue reminder.
14	PETAL BANQUET (A UNIT OF SHIV SHAKTI HOTELS PVT. LTD.)	21/18, NARAINA INDUSTRIAL AREA, PHASE-II	16-08-2016	DPCC/EC/2/1/2016/15867	BANQUET. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party	Orange Establish	Non-SPI		Source of water:DJB, Category-II (Copy of bill provided) water consumption:3500 litre/day Status of ground water:Nil MCD License valid up to 31.03.2017	.	30-08-2016 . Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 -As decided, an	04-11-2016 Consent to Establish granted.

					Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler					Status of Pollution Control System (1)ETP - proposed (2)ECS - channelization system with suitable stack provided on kitchen section (proposed) (3)D.G.Set: 2 D.G Sets of capacity 160 & 62.05 KVA (Proposed) Status of Ground Water extraction : Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details :No Closure directions u/s 31(A)/33(A)/5 of EPA details :No		inspection was conducted by DPCC officials on 02.11.2016 and following observations were made: -During inspection unit found non operational due to seasonal off. -ETP is under installation. -No channelisation provided in kitchen. -Two DG Set installed at roof top of the building found in acoustic enclosure. -Consent to establish applied on 16.08.2016. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 -Show cause notice was issued to the unit on 08.06.2016. - Unit submitted its reply on 23.06.2016 and requested for sometime to comply with the directions of DPCC. -An inspection was carried out by DPCC officials on 11.08.2016 and following observations were made: -ETP installed at roof top of the building was also under renovation. Last function was held at the premises on 27.07.2016. -Two D.G Set installed at roof top of the building in acoustic enclosure with adequate stack height. -Channelization provided in kitchen with adequate stack height. CTE & CTO not applied. -Modified direction
--	--	--	--	--	---	--	--	--	--	---	--	--

											issued to the unit on 29.09.2016.	
15	LAXMI PLASTIC	G-969, DSIDC NARELA INDUSTRIAL AREA	16-08-2016	DPCC/EC/2/1/2016/15902	MANUFACTURING OF PVC DANA WITH WASHING. Manufacturing of Reprocessed PVC Granules & Other Injection Moulded Items (using Scrap As Raw Material with Washing Activity)	Orange Establish	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- Yes 2. ECS- Yes (Stack connected to mixer) 3. D.G. set- No Plot Area- 350 sq.mt. Propsed Date-01.07.2004 Status of Ground Water Extraction-No 1. Water consumption- 4000 L/day. a) Source of water- DSIIDC (copy of DSIIDC water bill not submitted) Complaint against this unit made by Sh. Rohit Gupta. Status of Inspection- Yes(28.12.2015) Inspection findings- 1. Unit found operating and engaged in the activity of mfg. of plastic dana & plastic goods using plastic scrap as a raw material with trade effluent discharge. 2. No ECS installed. 3. No ETP installed and waste water is being discharged directly into sewer without any treatment. 4. Unit is operating without valid consent/ registration under air, water acts/plastic rules respectively. 5. One Borewell connection exists without permission from DJB/CGWA. Show cause notice for closure u/s 31 (A) of the Air, u/s 33 (A) of the Water Act, 1974 and u/s 5 of EPA issued on.22.02.2016. No reply received Directions for closure u/s 31 (A) of the Air, u/s 33 (A) of the Water Act, 1974 and u/s 5 of EPA issued on 28.04.2016	Water(Effluent)-N/A Emission monitoring report -N/A Noise Test Report- N/A	30-08-2016 - Remarks / ATR on 03-11-2016 SCN for refusal of consent issued on 24.10.2016. Letter to consent agencies seeking compliance of closure directions issued on 24.10.2016. Compliance is yet to be received. Recommendation / Action Taken Details (EE/AEE) on 27-09-2016 Inspection conducted on 19.09.2016 findings are as follows- 1. Unit found operating and engaged in the activity of mfg. of plastic dana & plastic goods using plastic scrap as a raw material with trade effluent discharge. 2. ETP found installed but not in operational condition and No wet and dry sludge seen. 3. ECS found installed with adequate stack height. 4. One Borewell connection exists without permission from DJB/CGWA. 5. HWM rules are not compiled with. Form 2 for registration under plastic rules submitted. Form 2 found incomplete and not as per the prescribed performa as per new Plastic rules 2016. As per Rule 13 (Registration of producer, recyclers and manufacturer) of Plastic rules 2016, further	04-11-2016 Reply awaited so case deferred.

sub-rule (5) says that The State Pollution Control Board or the Pollution Control Committee shall not issue or renew registration to plastic waste recycling or processing units unless the unit possesses a valid consent under the Water (Prevention and Control of Pollution) Act, 1974 (6 of 1974) and the Air (Prevention and Control of Pollution) Act, 1981 (14 of 1981) along with a certificate of registration issued by the District Industries Centre or any other Government agency authorised in this regard.

sub-rule (7) says that On receipt of the application complete in all respects for the registration for recycling or processing of plastic waste under sub-rule (3), the State Pollution Control Board may, after such inquiry as it considers necessary and on being satisfied that the applicant possesses appropriate facilities, technical capabilities and equipment to handle plastic waste safely, may grant registration to the applicant on fulfilment of the conditions as may be laid down in terms of registration.

sub-rule (8) says that Every State Pollution Control Board or Pollution Control Committee shall take a decision on the grant of registration within ninety days of

											receipt of an application which is complete in all respects. sub-rule (9) says that The registration granted under this rule shall initially be valid for a period of one year, unless revoked, suspended or cancelled and shall subsequently be granted for three years. Compliance of closure direction dated 28.04.2016 is not received from the concerened authorities.	
16	SUPER DENIM JEANS MFRG. COMPANY	K-16, SECTOR-5, BAWANA INDUSTRIAL AREA	19-08-2016	DPCC/EC/2/1/2016/15974	READYMADE JEANS WASHING. Readymade Garment (with Washing) Spray Painting, Paint Baking, Paint Stripping	Orange Establish	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- Proposed 2. ECS- N.A 3. D.G. set- No Plot Area- 250 sq mt Date of commissioning - October 2016 Status of Ground Water Extraction-No 1. Water consumption- 4400 L/day. a) Source of water- Outside (copy of Outside water bill not submitted) Status of Inspection- No	Effluent analysis report - N.A Emission moniotring report -N.A Noise monitoring report- N.A	27-09-2016 . Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Inspection conducted on 07.10.2016 Inspection Findings are- 1. Unit found in operation and engaged in the activity of Jeans dyeing and washing with spray painting work.(without boiler use). 2. ETP found installed but same is non-functional. No dry or wet sludge seen. Waste water is being discharged directly into sewer without any treatment. 3. HWM rules are not complied with. 4. Unit has applied for consent to establish but found operational without consent to operate. File is under submission with proposal SCN for refusal of consent and SCN for closure.	04-11-2016 Take action as decided in file.
17	LOVELY WASH CARE COMPANY	J-132, SECTOR-4, BAWANA	05-09-2016	DPCC/EC/2/1/2016/16067	READYMADE JEANS WASHING.	Orange Establish	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- Proposed	Effluent analysis report - N.A	27-09-2016 . Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Inspection conducted on 07.10.2016 Inspection Findings are- 1. Unit found in operation and engaged in the activity of Jeans dyeing and washing with spray painting work.(without boiler use). 2. ETP found installed but same is non-functional. No dry or wet sludge seen. Waste water is being discharged directly into sewer without any treatment. 3. HWM rules are not complied with. 4. Unit has applied for consent to establish but found operational without consent to operate. File is under submission with proposal SCN for refusal of consent and SCN for closure.	04-11-2016 Take action as per decision in file.

		INDUSTRIAL AREA			Readymade Garment (with Washing) with Boiler Spray Painting, Paint Baking, Paint Stripping				2. ECS- Proposed 3. D.G. set- No Plot Area- 250 sq mt Date of commissioning - October 2016 Status of Ground Water Extraction-No 1. Water consumption- 2000 L/day. a) Source of water- Outside (copy of Outside water bill not submitted) Status of Inspection- No	Emission moniotring report -N.A Noise monitoring report- N.A	Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Inspection conducted on 07.10.2016 Inspection Findings are- 1. Unit found in operation and engaged in the activity dyeing and washing of jeans with spray painting work.(without boiler use). 2.No ETP found installed and Waste water is being discharged without any treatment. 3. HWM rules are not complied with. 4. Unit is having two boiler. One is wood fired (400 kg/hour) which was in use.Another is diesel fired which is not in use. 5. Unit has applied for consent to establish but found operational without consent to operate. File is under submission with proposal SCN for refusal of consent and SCN for closure.	
18	SIKKA MOTORS PRIVATE LIMITED	B 99 WAZIRPUR INDUSTRIAL AREA	06-09-2016	DPCC/EC/2/1/2016/16080	AUTOMOBILE SERVICING AND REPAIR STATION WITH WASHING ACTIVITY. Automobile Servicing and Repair Station with Washing Activity	Orange Establish	Non-SPI		Status of Pollution Control System (1)ETP (proposed) (2)ECS - N/A (3)D.G.Set: 82.5 KVA with acoustic enclosure and stack height 3 m above roof level. Status of Ground Water extraction : Nil. Water Consumption : 2.3 KLD form corporation. Status of Inspection :The premises was inspected on 20.09.2016 with reference to complaint received through PGMS vide I.D. 201686083		28-09-2016 Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 premise was inspected on 20.09.2016 with reference to complaint received through PGMS vide I.D. 201686083 against M/s Himgiri Car Pvt.Ltd. (having consent to operate & authorisation under HWM Rules valid up to 21.03.2017). However during inspection it was	04-11-2016 Reply awaited so case deferred.

									against M/s Himgiri Cars Pvt. Ltd. and following were observed: -The unit has installed an Effluent Treatment Plant, but the same was not in operation since long. -No wet sludge was observed. -Used engine oil was scattered on the top floor of the premises. -No filter media was observed in sludge drying bed. -Dry sludge alongwith general waste was found stored at roof top of the building in 3-4 drums. -Non-compliance of hazardous waste rule observed. During the inspection it was reported that now the unit is being run in the name of M/s Sikka Motors Pvt. Ltd. The file is under submission for further necessary action.		reported that now the unit is being run in the name of M/s Sikka Motors Pvt. Ltd. During the inspection following were observed: -The unit has installed an Effluent Treatment Plant, but the same was not in operation since long. -No wet sludge was observed. -Used engine oil was scattered on the top floor of the premises. -No filter media was observed in sludge drying bed. -Dry sludge alongwith general waste was found stored at roof top of the building in 3-4 drums. -Non-compliance of hazardous waste rules observed. As approved in file, Show Cause Notice u/s 33(A) of the Water Act & u/s 5 of the EP Act, Show Cause Notice for revocation of consent to operate and Show Cause Notice for cancellation/ withdrawal of authorization under HWM rules issued on 03.11.2016.
19	TIVOLI PUSHPANJALI (A UNIT OF T.G. LEISURE AND RESORTS PVT LTD)	F 20 PUSHPANJALI DWARKA LINK ROAD BIJWASAN	08-09-2016	DPCC/EC/2/1/2016/16108	BANQUET HALL PARTY LAWN. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - not connected to / Discharging Effluent	Orange Establish	Non-SPI		Status of Pollution Control System (1) STP (Proposed) (2)ECS - N/A (3)D.G.Set: 1 (125 KVA) Status of Ground Water extraction : Water Consumption: 1780 ltrs/day, Source: Outside. Status of Inspection : Unit was inspected by the officials of DPCC on 10.08.2016 during visit to the area. The unit was found in operating without	. 27-09-2016 Applied for Consent to Establish on 08.09.2016. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 File under submission.	04-11-2016 Modified directions u/s 31(A) of Air Act & 33(A) of Water Act issued on 04.11.2016. Case deferred.

					into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler				any CTE/CTO and without any ETP/STP. Following were the observations during the inspection:- -It was informed that the party lawn had started their operation approx. 6-7 months back. -No ETP/STP found attached. -The acoustic enclosure attached with DG Set was not proper as Gates of DG Set were found broken. SCN u/s 31(A) of Air Act & 33(A) of Water Act and also for Refusal of Consent to Operate was issued to unit on 29.08.2016 w.r.t deficiencies observed during inspection. Unit has submitted its reply on 14.09.2016 w.r.t SCN issued to unit on 29.08.2016 that the unit has applied for CTE on 08.09.2016 and requested 90 days time to submit CTO.			
20	HIMGIRI AUTO (INDIA) PRIVATE LIMITED	A-9/1, JHILMIL INDUSTRIAL AREA	12-09-2016	DPCC/EC/2/1/2016/16124	CAR WASHING AND SERVICES. Automobile Servicing and Repair Station with Washing Activity with burner	Orange Establish	Non-SPI		Status of Pollution Control System (1)ETP - Proposed unit. (2)ECS - N/A (3)D.G.Set: one no 180 KVA		17-10-2016 Recommended for grant for CTE.	04-11-2016 Consent to Establish granted.
21	ARIHANT MARKETING (INDIA)	PLOT NO A-17, LAWRENCE ROAD INDUSTRIAL AREA	15-09-2016	DPCC/EC/2/1/2016/16148	MINERALISED WATER/WATER TREATMENT PLANT. Mineralised Water/Water Treatment Plant	Orange Establish	Non-SPI		(1)ETP ---- Proposed (2)D.G.Set Noise Report : N/A (3)Status of Ground Water extraction : outside source (4)Status of Inspection :N/A (5)SCN u/s 31(A)/33(A)/5 of EPA details : N/A (6)Closure directions u/s 31(A)/33(A)/5 of EPA details : N/A (7) Activity is not mentioned clearly. (8) Commencement 30.09.2016.	N/A	29-09-2016 Category of the unit is II (b). Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Inspection has been conducted on 07-10-2016. The unit is engaged in the activity of mineralised water/water treatment plant. ETP has been installed by the unit and it was informed that earlier ETP was installed and the same has been removed now. Waste water is generated from RO wastage and sand	04-11-2016 Issue show cause notice for refusal of consent, show cause notice u/s 31(A) of Air Act and u/s 33(A) of Water Act.

											filter back washing process. The unit is also manufacturing packaged glass water. No DG set was found. One borewell for groundwater extraction was also found in the premises and no permission was shown. The unit is also manufacturing PET glasses with printing activity. Plastic and aluminium scrap was found stored in the premises.	
22	AMBUJ AUTOMOBILE	501, FIE, PATPARGANJ INDUSTRIAL AREA	16-09-2016	DPCC/EC/2/1/2016/16153	SERVICE STATION OF VEHICLES (BIKES). Automobile Servicing and Repair Station with Washing Activity	Orange Establish	Non-SPI		Status of Pollution Control System (1)ETP ---- Proposed unit. ETP needs to be installed. (2)ECS - N/A (3)D.G.Set: One no. 65KVA Status of Ground Water extraction :Nil	NA	17-10-2016 Recommended for grant of Consent to Establish. Remarks/ATR on 04-11-2016 Inspection of the unit was conducted on 03.11.2016 and following were observed: 1. The unit i.e Service station for two wheeler is under establishment. Different tools and plants have been found installed/erected but yet to be commissioned. 2. ETP based on Physio-Chemical treatment consists of collection cum equalization tank, reaction cum settling tank, clear water tank besides MGF and ACF and two Sludge drying beds were found installed. But same is yet to be started as no trade effluent is generated due no commissioning of the service station. Recommended for grant of Consent to Establish.	04-11-2016 Consent to Establish granted.
23	S.A.S.	B-108,	21-09-2016	DPCC/EC/2/1/2016/16194	READYMADE JEANS	Orange	Non-SPI		Status of Pollution Control	Air (Emission)-N/A	03-11-2016	04-11-2016

	COLOUR IMPACT	SECTOR-2, DSI IDC, BAWANA INDUSTRIAL AREA			WASHING. Readymade Garment (with Washing)	Establish			system Devices- 1. ETP-Yes 2. ECS- Yes (Kitchen emission channelization) 3. D.G. set- No Plot Area-100 sq mt Date of Establishment - 01.09.2010 Status of Ground Water Extraction-No (As per consent form). Yes (as per previous inspection). 1.Water consumption- 4400 L/day. Source- DSI IDC (bill submitted) Status of Inspection- Yes (14.01.2016) 1. Unit found operating & engaged in the activity of Jeans washing. 2. No valid consent obtained from DPCC. 3. One borewell connection exists without permission from DJB/CGWA. 4. No ETP installed waste water is being discharged directly into sewer without any treatment. Show Cause Notice u/s 31 (A) of Air Act & 33(A) of Water Act issued on 24.02.2016 (in name of Yes a Yes Colour Impact Company). No Reply was submitted. Directions for closure issued on 29.04.2016(in name of Yes a Yes Colour Impact Company). Unit was again inspected on 01.09.2016 to check the operational status. During inspection, unit found operational & engaged in the activity of Jeans washing, No ETP installed & waste water is being discharged directly without any treatment, HWM Rules are not complied with, No ECS installed over spray paint booth. Spray paint work not shown in consent applications. Compliance of closure directions yet to be received. Unit vide its letter on 27.09.2016 has requested for revocation of closure directions.	Water (Effluent)- Test Report (readymade garment washing) issued on 22.08.2016 by DPCC lab submitted. Parameters are within prescribed limit. Noise Test Report- N/A	-	Issue show cause notice for refusal of consent. Also seek compliance report from concerned agencies.
24	THE GRACE (	A-25,	23-09-2016	DPCC/EC/2/1/2016/16213	BANQUET HALL.	Orange	Non-SPI		Source of water: DJB,	.	03-11-2016	04-11-2016

A UNIT OF M/S MALHOTRA RELATECH PVT. LTD.)	NARAINA INDUSTRIAL AREA, PHASE- II	Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Establish	Category-II (Copy of bill enclosed) Water Consumption: 8000 litre/day Extraction of Ground Water: Nil D.G Set: 1 D.G Set of 250 KVA installed Status of Pollution Control System (1)ETP -proposed (2)ECS - N/A -A complaint received in this office on 02.11.2015. -Accordingly, an inspection was conducted by DPCC officials on 28.01.2016 and following observations were made: -Effluent treatment plant has been installed but the same was not operational since long. -Sludge drying bed of ETP found stored with utensils. -No log book with respect to operation of ETP shown. -Stack height of DG Sets and stack height of hoods in kitchen area, found inadequate. -One borewell exist but no permission in this regard was shown. -Three party halls exist in the said premises on ground floor, first floor and second floor. -As decided, a show cause notice u/s 33(A) of Water Act, 1974 and u/s 31(A) of Air Act, 1981 was issued to the unit on 29.02.2016. -Unit submit its reply in response to our SCN and stated that all the deficiencies observed during inspection were rectified and also requested for one month time for submitting consent to establish application. -Modified direction u/s 33(A) of Water Act, 1974 and u/s 31(A) of Air Act, 1981 was issued to the unit on 08.06.2016 giving 45 days.	Consent to Establish granted.
--	---	--	-----------	---	-------------------------------

									-Unit has failed to submit any reply w.r.t modified direction. -As decided, a closure direction u/s 33(A) of Water Act, 1974 and u/s 31(A) of Air Act, 1981 issued to the unit on 11.08.2016. -Unit again submits its reply on 28.08.2016 and 13.10.2016 along with the copy of consent to establish application vide ID 16213 and requested for revocation of closure direction. -As decided by the Competent Authority, DPCC closure direction was revoked temporarily for 30 days date 25.10.2016 .			
25	NATIONAL SERVICE STATION	KHASRA NO 28, A BLOCK, WAZIRPUR	26-09-2016	DPCC/EC/2/1/2016/16220	SERVICING,REPAIRING AND WASHING OF LIGHT VEHICLES. Automobile Fuel Outlet (with Automobile Servicing, Washing, Repairing and Painting)	Orange Establish	Non-SPI		-ETP :proposed. -ECS :Nil -Water source:2.2 KLD from outside source (water tank) -Ground water:nil -DG set:nil -Proposed Year of Commencement:January 2017		02-11-2016	04-11-2016 Ask the unit to submit proof of conformity w.r.t. MPD-2021 for the activity of Petrol Pump cum Service Station for automobiles.
26	S.K. ROYAL OMATE (A UNIT OF S.K. FOODS AND BEVERAGES)	A-47, MAYAPURI INDUSTRIAL AREA, PHASE-I	27-09-2016	DPCC/EC/2/1/2016/16238	BANQUET HALL. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Establish	Non-SPI		Source of water: DJB, Category-II (Copy of bill enclosed) Water Consumption: 3000 litre/day Extraction of Ground Water: Nil D.G Set: 2 D.G Sets of capacity 125 KVA (proposed) Status of Pollution Control System (1)ETP - Proposed (2)ECS - Proposed Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details :No Closure directions u/s 31(A)/33(A)/5 of EPA details :No		03-11-2016	04-11-2016 Consent to Establish granted with the condition that the unit shall apply for Consent to Operate within 03 months.
27	BIKANERVALA FOODS PVT LTD	A 27 LAWTRACE ROAD INDUSTRIAL AREA	28-09-2016	DPCC/EC/2/1/2016/16249	MFG. OF SWEETS BAKERY PRODUCTS AND VEGETABLE FOODS. Restaurants/Eating Houses / Dhabas and	Orange Establish	Non-SPI		(1) ETP Proposed (2))ECS - N/A (3) D.G.Set ..250 KVA with stack height 3 m above roof level.	The unit is already in operation and no consent to operate application has been filed by the unit with consent to establish. No test reports either submitted.	02-11-2016 The unit may be inspected for premises no A 14 and A 16 Lawrence Road Ind Area before taking	04-11-2016 Consent to Establish granted. Subsequently, inspection be conducted.

					other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler				(4) Source of water 6.5 KLD from Municipal Authority. (5) Earlier the unit has applied for consent to establish and operate for BIKANERVALA FOODS PVT. LTD. A 16, LAWRENCE ROAD INDUSTRIAL AREA NEW DELHI 110035, vide 2969 dated 01.11.2012 and vide ID 3317 07.01.2013. The decision taken was Consent to Establish in the light of latest RESDH policy granted for Mfg. of Sweets, Bakery Products and Vegetable Foods. On 19.02.2013 it was decided that Consent to Operate granted. IT Cell be requested to correct the category of the activity of the unit as per latest RESDH policy before issue of consent for BIKANER WALA POODS. PVT. LTD , A 14, LAWRENCE ROAD INDUSTRIAL AREA, DELHI 110035 having ID 31589 dated 30.09.2009 for MFG OF NAMKEENS, SWEETS & BAKERY ITEMS and the unit has not applied	further action as per remarks above.		
28	GOLDEN GATE BANQUETS	B-18, MAYAPURI INDUSTRIAL AREA	06-10-2016	DPCC/EC/2/1/2016/16270	Banquet Hall Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Establish	Non-SPI		Status of Pollution Control System Water Consumption: 5000 Litres/ Day Source of Water: Outside Status of Ground Water extraction : Nil (1)ETP ---- ETP - Physiochemical,Oil and Grease Trap (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	03-11-2016	04-11-2016 Unit has submitted a letter on 04.11.2016 stating that erection of the ETP is nearing completion and the same will be submitted latest by 06.11.2016 and requested to revoke the directions for closure for submission of consent to operate application. Consent to establish granted and directions for closure be revoked temporarily for 45 days after submission of requisite security bond and undertaking as per office order dated 18.06.2015 for submission of consent to operate application along with requisite documents and test report(s).	
29	DURATUF GLASS	S-59,60,PH-1,BADLI INDUSTRIAL	07-10-2016	DPCC/EC/2/1/2016/16271	Manufacturing of Toughened Glass	Orange Establish	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- No	Effluent analysis report - No	03-11-2016	04-11-2016 Modified directions be issued for

	INDUSTRIES PVT. LTD	ESTATE,DELHI- 110042			Glass Processing (Cutting, Grinding, Polishing etc.) with Trade Effluent Discharge and without Furnace				2. ECS- No 3. D.G. set- N/A Plot Area- 1000 sq mt (S 60 is 620 sq yd. and S 59 is 527 m) Date of Commissioning- 29.11. 2016 Status of Ground Water Extraction-No 1. Water consumption- 4400 L/day. a) Source of water- Outside(copy of outside water bill not submitted) Status of Inspection- No. However, DPCC lab inspected the unit and lifted the treated sample of waste water on 04.01.2016 and meeting the norms. Show cause notice for closure u/s 33 (A) of the Water Act, 1974 and u/s 31(A) of the Air Act, 1981 issued on 03.08.2016 as unit is operational without valid consent. No reply received in response to SCN, however, CTE applied and shown its commencement on 29.11.2016.	Emission monitoring report - No Noise monitoring report - N/A		submission of consent to operate application incorporating the issue of date of establishment and consent fee within 30 days. Also inspection be conducted.
30	MANMACHINE WORKS PVT LTD	GOLDEN PARK, RAMPURA, ROHTAK ROAD, DELHI	07-10-2016	DPCC/EC/2/1/2016/16272	filling station cum service station Automobile Fuel Outlet (with Automobile Servicing, Washing, Repairing and Painting)	Orange Establish	Non-SPI		Status of Pollution Control System (1)ETP ---- installed having capacity 3 KLD (a) Oil and Grease Trap (b) ETP is also installed (2)ECS - N/A (3)D.G.Set: ... after jan 2005, 65 KVA with stack height 2 m above roof level (4) Source of water ---- Other 2.5 KLD (5) Allotment letter for land for filling cum service station dated 01-08-1994 submitted. (6) License from Chief controller of Explosive for storing petrol in tanks is also submitted.	N/A	03-11-2016 N/A	04-11-2016 Consent to Establish granted.

									(7) Total plot area 36 and 30 is equal to 1080 SQM.			
31	PARDEEP KUMAR MISHRA	11, TOP FLOOR, S.S.I. INDUSTRIAL AREA, G.T.K. ROAD, DELHI - 110033	19-10-2016	DPCC/EC/2/1/2016/16306	Stainless Steel Utensils with Buffing Manufacturing of Stainless Steel Utensils (with Buffing Activity)	Orange Establish	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- N/A 2. ECS- N/A 3. D.G. set- N/A Plot Area- 100 sq mt Date of Commissioning- 01.11.2016 Status of Ground Water Extraction-No 1. Water consumption-100 L/day. a) Source of water- Outside(copy of outside water bill not submitted) Status of Inspection- No	Effluent analysis report - N/A Emission monitoring report - N/A Noise monitoring report - N/A	04-11-2016 -	04-11-2016 Consent to Establish granted. Subsequently, inspection be conducted.
32	LANDMARK LIFESTYLE CAR PVT. LTD.	PLOT NO-10A,SHIVAJI MARG	20-10-2016	DPCC/EC/2/1/2016/16311	Service Statio of jeep cars Automobile Servicing and Repair Station with Washing Activity	Orange Establish	Non-SPI		Source of Water: Ground Water (copy of water cess bill provided) Water Consumption:5800 Litres/ Day Status of Ground Water extraction : No Status of Pollution Control System (1)ETP ---- N/A (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	(a) Effluent analysis report dated 14-09-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes	03-11-2016 Consent to establish may be granted.	04-11-2016 Consent to Establish granted.
33	MEHAR OVERSEAS	A 27 BADLI INDUSTRIAL ESTATE PH III	28-10-2016	DPCC/EC/2/1/2016/16345	Mfg. of Mahendi Manufacturing of Kali Mehandi / Hair Colour in Powder form (Grinding and mixing only)	Orange Establish	Non-SPI		Status of Pollution Control system Devices- 1. ETP-N/A 2. ECS-Yes, attached to mixing cum ball mill machine 3. D.G. set- 1x62.5 KVA Plot Area-249.78 sq mt Date of Commencement- 15.04.2004 Status of Ground Water Extraction-Yes 1.Water consumption- 600 L/day. Source- Ground water (ground water charges bill to DJB submitted) Status of Inspection- No As per enquiry counter remarks in the receipt unit has created its user ID itself and applied for CTE online with condition fee	Effluent monitoring report - N/A Emission monitoring report- No Noise monitoring report - No	03-11-2016 -	04-11-2016 Consent to Establish granted.

										w.e.f. 01.06.1991. Unit has submitted request letter to cancel another user ID created by unit.				
--	--	--	--	--	--	--	--	--	--	---	--	--	--	--



CONSENT MANAGEMENT

Decisions taken by the Committee for II(b) Category cases headed by Member Secretary DPCC in its 15th meeting on 04.11.2016 w.r.t. Agenda Item No 1 -- 74 Pending Cases of Consent to Operate / Renewal of the period 01.04.2016 to 31.10.2016 (Annexure II).

S. No.	Industry Name	Address	Date of Application	Application No	Activities / Product	Consent Application [CTE / CTO / CTO(R)]	Category (SPI/Non SPI)	Authorization Status (Granted/Applied - Fresh/Renewal)	Brief of Case	Status of Test Report(s)	Remarks (Whether unit fulfills all conditions for grant of Consent / Authorisation)	Decison
1	AGGARWAL AUTOMOTIVE PVT. LTD	PLOT NO-2, RAJASTHAN UDYOG NAGAR INDUSTRIAL AREA	07-04-2016	DPCC/EC/2/1/2016/14217	MFG. OF AUTOMOBILE REPAIR WITH WASHING. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 07-04-2016 Authorisation Status Pending	Status of Pollution Control system/Devices: 1. ETP- Yes(4KLD) a) Adequacy report of ETP dated December, 2015 issued by Jamia Millia submitted 2. ECS-No 3. D.G. set- Yes, 1x 62.5 KVA Plot Area- 2150 sq.mt. Proposed Date- 25.03.2015 Status of Ground Water Extraction:No 1. Water consumption: 4900 L/day. a) Source of water: Outside (copy of Outside water bill not submitted) Status of Inspection: No	Effluent analysis report of outlet of ETP dated 06.11.2015 issued by Shriram Institute For Industrial Research submitted. Parameters are within prescribed limit. Air (Emission)- N/A Noise monitoring report dated 06.11.2015 issued by Centre for Occupational and Environmental Health(IVPSS) submitted. Parameters are within prescribed limit.	06-07-2016 - Remarks/ATR on 04-11-2016 Show cause notice for closure u/s 33(A) of Water Act, u/s 31(A) of Air Act and u/s 5 of EPA for closure of the unit issued on 29.09.2016. Remarks/ATR on 20-09-2016 Inspection conducted on 05.09.2016. Inspection Findings are- 1. Unit found in operation and engaged in the activity of automobile repairing and servicing with washing. 2. ETP found installed but not in operational condition. Trade effluent is discharging into sewer without any treatment. 3. Stack provided with paint booth but with inadequate stack height. 4. HWM rules are not complied with.	04-11-2016 Issue show cause notice for refusal of consent/authorization.
2	YASH INDUSTRIES	T-7, KH. NO 29, BALAJI GALI, NEW MANDOLI	13-04-2016	DPCC/EC/2/1/2016/14286	MANUFACTURING OF COPPER INGOTS. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		A Notice u/s 31(A) of Air (Prevention & Control of Pollution) Act, 1981 was issued on 02.06.2015. Reply received on 16.06.2015, informing the submission of adequacy report and Air monitoring report but the letter was without enclosures as claimed. As approved the	AR dated 10.04.2012 issued by DTU submitted. Stack monitoring report dated 16-05-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes number of parameters analyzed which are within limit / beyond prescribed limit.	12-07-2016 Redevelopment Area. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Letter has been issued to the unit on 03.11.2016 for submitting the	04-11-2016 Expedite inspection.

									Closure Directions u/s 31(A) of Air (Prevention & Control of Pollution) Act, 1981 was issued accordingly to the unit on 16.07.2015. The Closure Directions u/s 31(A) of Air (Prevention & Control of Pollution) Act, 1981 was again issued to the unit on 28.09.2015. unit was sealed by SDM on 17.10.2015. A representation was received from the unit on 19.10.2015 requesting for de-sealed & unit have submitted Security bond Rs. 5, 00,000/- A representation was received from the unit on 13.04.2016 requesting for de-sealed & unit have applied for CTO. Temporary Revocation of Direction of Closure for 15 days was issued on 19.04.2016 directing to submitting the stack Monitoring Report etc. Stack monitoring report conducted on 12.05.2016 received, the value of analyed parameter was found within the prescribed limit. (1)ETP ---- N/A (2)ECS - Wet Scrubber and Cylcone (3)D.G.Set Noise Report : N/A (4) water Consumption: 40 Liter/ Day Source: Cane Water (5) Ground Water: Nil		certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit, for installation of online monitoring system and for submitting the remaining fees for another 4 years. Inspection yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Case deferred decision in CMC meeting held on 12.07.2016	
3	SABHARWAL AUTOMOBILES	KH NO 1144 VILLAGE RITHALA INDUSTRIAL AREA	15-04-2016		REPAIR AND MAINTENANCE OF TWO WHEELERS ONLY WITH WASHING Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 15-04-2016 Authorisation Status Pending	(1)ETP ---- Yes (2)ECS - N/A (3)D.G.Set: ...N/A... (4)Status of Inspection :N/A (5)SCN u/s 31(A)/33(A)/5 of EPA details :N/A (6)Closure directions u/s 31(A)/33(A)/5 of EPA details :N/A (7)The unit has not submitted hard copies of the application for consent and HWM as yet.	Not submitted	20-09-2016 Unit has not submitted its hard copies of the consent application and HWM application till date. Test report also not submitted. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 As decided unit has been issued a letter	04-11-2016 Issue show cause notice for refusal of consent, show cause notice u/s 33(A) of Water Act and show cause notice u/s 5 of EP Act to M/s Sabharwal Automobiles. Also seek the hard copy of consent application. Issue show casuse notice u/s 31(A) of Air Act, show cause notice u/s 33(A) of Water Act and show cause notice u/s 5 of EP Act to M/s Metro Motors.

											regarding submission of hard copies of consent application along with required documents within 15 days on 25-10-2016. Reply is awaited. Letter to submit certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit has also been handed over to the unit on 03.11.16. Inspection of the unit also done on 03.11.16 and the ETP of the unit was found in defunct and disconnected condition. Trade effluent was being discharged into open drain. No measures for the management of hazardous waste were taken by the unit as observed during inspection. Other unit M/s Metro Motors at the same premises which is polluting and engaged in servicing of vehicles was found and this unit ETP was in defunct / disconnected condition. No HWM measures. A dg set of 45 kva was with acoustic enclosure but with inadequate stack height.	
4	J. P. INDUSTRIES	BLOCK-A, SHED NO. 8, DSIDC, JHILMIL INDUSTRIAL AREA	19-04-2016	DPCC/EC/2/1/2016/14368	COPPER WIRE DRAWING AND SUPER ENAMELLED WIRE. Copper Wire Drawing with Super Enamelling (Dry Process)	Orange Renewal	Non-SPI	HWM Application No. 1 Application Date 25-04-2016 Authorisation Status Pending	(1)ETP ---- N/A (2)ECS - Catalytic Converter (3)D.G.Set Noise Report : 1 (4) water Consumption: 200 Litres/ Day Source: MCD Water (5) Ground Water: Nil	AR : N/A Stack monitoring report dated 28-01-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. The value of parameter analysed found within the prescribed limit. The unit has 1 D.G. Set(s) of 125 KVA. Noise monitoring report dated 28-01-2016 issued by FICCI RESEARCH ANALYSIS CENTRE	12-07-2016 Recommended for CTO and inspection thereafter. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Inspection of the unit was conducted on 03.11.2016 and following were observed:	04-11-2016 Issue show cause notice for refusal of consent / authorization, show cause notice u/s 31(A) of Air Act and u/s 5 of EP Act.

										submitted. Noise monitoring report within Limit - Yes number of parameters analyzed which are within prescribed limit.	1. The unit was found in operation. At ground floor in a portion super enameling plant is exist in half portion non operative super enameling plant also exist in non operative condition and in front room in that portion 2 wire drawing machines exist carrying wire drawing. 2. Super enameling process was going on as informed that a catalytic converter as ECS is installed with the enamelling plant, however significant fugitive emissions were existing during the process which have not been channelized properly. 3. At roof top vertical furnace duct , the emissions being found dispersed by exhaust fan, also two ducts with the said furnace with inadequate height provided. 4. The Hazardous Waste Management was found not maintained. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection yet to be conducted.	
5	AGGARWAL PLACTICS	G-1028, DSIDC NARELA INDUSTRIAL AREA	22-04-2016	DPCC/EC/2/1/2016/14410	MANUFACTURING OF PVC DANA WITH WASHING. Manufacturing of Reprocessed PVC Granules & Other Injection Moulded Items (using Scrap As Raw Material with Washing Activity)	Orange Operate	Non-SPI		Status of Pollution Control system/Devices: 1. ETP- Yes 2. ECS-Yes 3. D.G. set- No Plot Area- 350 sq.mt. Proposed Date- 17.05.2016 Status of Ground Water Extraction:No 1. Water consumption: 3000 L/day. a) Source of water: Outside (copy of Outside water bill submitted) Application for registration form 2 under plastic rules submitted. Status of Inspection: Yes Inspection was conducted on 12.03.15 by the officials of DPCC and inspection findings are as follows: 1. Unit found operating	Effluent analysis report of outlet of ETP dated 07.01.2016.2016 issued by Shriram Institute For Industrial Research submitted. All Parameters are within prescribed limit except BOD i.e.. not detected & Total Metals which is not mentioned in the report. Emission monitoring report dated 14.01.2016 issued by Shriram Institute For Industrial Research submitted. Parameters are within prescribed limit. Noise Test Report- N/A	06-07-2016 - Remarks/ATR on 03-11-2016 Letter issued on 25.07.2016 to submit fresh complete effluent analysis report of ETP from em-panelled laboratory of DPCC. Unit replied on 20.09.2016 wherein submitting effluent analysis report on 19.09.2016 issued by DPCC. Parameters are within prescribed limit. As per, DPCC test report no. 767 dated 19.09.2016, total metal parameter	04-11-2016 Expedite inspection. Ask the Lab, DPCC to clarify the value of total metal. Ask the unit to apply fresh authorization under Plastic Waste Rules 2016 along with certificate of registration issued by Industries Department.

										and engaged in the activity of mfg. of PVC conduit pipes by reprocessing. 2.Effluent from washing of scrap being discharged w/o any treatment. 3.One Borewell exists, copy of application for voluntary disclosure shown. Notice for closure u/s 31 (A) of Air Act, u/s 33(A) of Water Act and u/s 5 of EPA (Plastic Rules) issued to M/s Aggarwal Plastics on 19.08.2015 . Another Notice u/s 31(A) of Air Act, 33(A) of Water Act & u/s 5 of EPA giving 15 days time for compliance may be issued failing which closure will issued on 01.02.2016			is analysed but value is not mentioned. Form 2 for registration under plastic rules submitted. Form 2 found incomplete and not as per the prescribed per forma as per new Plastic rules 2016. As per Rule 13 (Registration of producer, recyclers and manufacturer) of Plastic rules 2016, further sub-rule (5) says that The State Pollution Control Board or the Pollution Control Committee shall not issue or renew registration to plastic waste recycling or processing units unless the unit possesses a valid consent under the Water (Prevention and Control of Pollution) Act, 1974 (6 of 1974) and the Air (Prevention and Control of Pollution) Act, 1981 (14 of 1981) along with a certificate of registration issued by the District Industries Centre or any other Government agency authorised in this regard. sub-rule (7) says that On receipt of the application complete in all respects for the registration for recycling or processing of plastic waste under sub-rule (3), the State Pollution Control Board may, after such inquiry as it considers necessary and on being satisfied that the applicant possesses appropriate facilities, technical capabilities and equipment to handle plastic waste safely, may grant registration to the applicant on fulfilment of the conditions as may be laid down in terms of registration. sub-rule (8) says that	
--	--	--	--	--	--	--	--	--	--	--	--	--	---	--

											Every State Pollution Control Board or Pollution Control Committee shall take a decision on the grant of registration within ninety days of receipt of an application which is complete in all respects. sub-rule (9) says that The registration granted under this rule shall initially be valid for a period of one year, unless revoked, suspended or cancelled and shall subsequently be granted for three years. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Letter issued on 25.07.2016 to submit fresh complete effluent analysis report of ETP from empanelled laboratory of DPCC. Unit replied on 20.09.2016 wherein submitting effluent analysis report on 19.09.2016 issued by DPCC. Parameters are within prescribed limit.	
6	UPPER INDIA TRADING CO. (DELHI) PVT LTD.	PLOT NO. 49 (C & D) RAMA ROAD, NAJAFGARH ROAD INDUSTRIAL AREA	29-04-2016	DPCC/EC/2/1/2016/14523	SERVICE STATION OF TWO WHEELERS WITH WASHING. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 29-04-2016 Authorisation Status Pending HWM Application No. 2 Application Date 29-04-2016 Authorisation Status Pending	Source of Water-Outside (copy of bill not provided)0 Water Consumption-4000 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP ---- Working (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	Water Effluent-Effluent analysis report dated 05-02-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes	11-07-2016 copy of outside purchase water bill not provided. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 As approved, an inspection was carried out by the representative of DPCC on 24.10.2016 and following observations were made: -ETP installed and also was operational. -HWM guidelines found followed. -Used oil being sold out to the registered recycler. -Applied for CTO and Authorization under HWM Rules.	04-11-2016 Consent to Operate and Authorization under HWM Rules granted. IT Cell be asked to deactivate the authorization application Dated 29.04.2016 which is duplicate entry.

											Consent to operate may be granted.	
7	ASHWANI PLASTIC	C-516, NARELA INDUSTRIAL AREA	02-05-2016	DPCC/EC/2/1/2016/14535	MANUFACTURING OF PLASTIC DANA WITH WASHING. Manufacturing of Reprocessed PVC Granules & Other Injection Moulded Items (using Scrap As Raw Material with Washing Activity)	Orange Operate	Non-SPI		Status of Pollution Control system/Devices: 1. ETP- Yes 2. ECS-Yes 3. D.G. set- No Plot Area- 350 sq.mt. Proposed Date- 06.05.2015 Status of Ground Water Extraction:No 1. Water consumption: 4000 L/day. a) Source of water: Outside (copy of Outside water bill submitted) Status of Inspection: Yes Inspection was conducted on 12.03.15 by the officials of DPCC and inspection findings are as follows: Unit namely Ashwani Plastic found operating engaged in reprocessing of plastic with trade effluent discharge without ETP and without consent/ registration from DPCC. One borewell exist w/o permission SCN u/s 31(A) of Air Act, 33(A) of Water Act & u/s 5 of EPA issued on 30.04.2015 Modified Direction u/s 31(A) of Air Act, 33(A) of Water Act & u/s 5 of EPA giving 45 days time to apply for consent/authorization issued on 08.12.2015. Replied on 11.03.2016, water & air sampling reports attached and requested to give one month time to give adequacy report. Application for registration form 2 under plastic rules submitted.	Effluent analysis report of outlet of ETP dated 18.01.2016 issued by Shriram Institute For Industrial Research submitted. All Parameters are within prescribed limit except total metal which is not mentioned in the test report. Emission monitoring report dated 14.01.2016 issued by Shriram Institute For Industrial Research submitted. Parameters are within prescribed limit. Noise Test Report- N/A	06-07-2016 - Remarks/ATR on 03-11-2016 Inspection is yet to be conducted. Form 2 for registration under plastic rules submitted. Form 2 found incomplete and not as per the prescribed performa as per new Plastic rules 2016. As per Rule 13 (Registration of producer, recyclers and manufacturer) of Plastic rules 2016, further sub-rule (5) says that The State Pollution Control Board or the Pollution Control Committee shall not issue or renew registration to plastic waste recycling or processing units unless the unit possesses a valid consent under the Water (Prevention and Control of Pollution) Act, 1974 (6 of 1974) and the Air (Prevention and Control of Pollution) Act, 1981 (14 of 1981) along with a certificate of registration issued by the District Industries Centre or any other Government agency authorised in this regard. sub-rule (7) says that On receipt of the application complete in all respects for the registration for recycling or processing of plastic waste under sub-rule (3), the State Pollution Control Board may, after such inquiry as it considers necessary and on being satisfied that the applicant possesses appropriate facilities,	04-11-2016 Expedite inspection. Ask the unit to apply fresh authorization under Plastic Waste Rules 2016 along with certificate of registration issued by Industries Department.

											technical capabilities and equipment to handle plastic waste safely, may grant registration to the applicant on fulfilment of the conditions as may be laid down in terms of registration. sub-rule (8) says that Every State Pollution Control Board or Pollution Control Committee shall take a decision on the grant of registration within ninety days of receipt of an application which is complete in all respects. sub-rule (9) says that The registration granted under this rule shall initially be valid for a period of one year, unless revoked, suspended or cancelled and shall subsequently be granted for three years. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Letter issued on 25.07.2016 to submit fresh complete effluent analysis report of ETP from empanelled laboratory of DPCC. Unit submitted effluent analysis report on 07.09.2016 issued by DPCC. Parameters are within prescribed limit.	
8	MAHADEV INDUSTRIES	L-7 KHASRA NO 77 HANUMAN GALI, NEW MANDOLI INDUSTRIAL AREA	09-05-2016	DPCC/EC/2/1/2016/14621	CASTING OF FERROUS / NON FERROUS METAL (EXXPET COUPLA FURNANCE ONLY). Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Scrubber, Cyclone (3)D.G.Set Noise Report : 1 (4) Water Consumption: 200 ltr/ day Source: out source (5) Ground Water: Nil	AR : Nil Stack monitoring report dated 25-04-2016 issued by DPCC submitted. The unit has 1 D.G. Set(s) of 125 KVA. Noise monitoring report dated 12-04-2016 issued by DPCC submitted.	12-07-2016 Redevelopment Area. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Letter has been issued to the unit on 02.11.2016 for submitting the certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area	04-11-2016 Expedite inspection.

											clearly mentioning the name & address of the unit and for installation of online monitoring system. Inspection yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Case deferred decision in CMC meeting held on 12.07.2016	
9	ADVIKA METALS	KHASRA NO. 18/21, MANDOLI INDUSTRIAL AREA, SHAHDRA	11-05-2016	DPCC/EC/2/1/2016/14650	copper wire rod manufacturing Copper / Aluminium Re-Rolling Industry(Foils and Strips Etc.) with Capacity less than 25MT/Day	Orange Operate	Non-SPI		Based upon the deficiencies found during the inspection conducted on 11.01.2016 in a PGC case, a SCN u/s 33 (A) of Water Act, 1974 and u/s 31 (A) of Air Act, 1981 was issued on 22.04.2016. Reply was submitted by the unit requested for time for installation of OLMS. (1)ETP ---- N/A (2)ECS - Scrubber, Cyclone (3)D.G.Set Noise Report : 1 (4) Water Consumption: 300 Liters/ Day Source: Outside (5) Ground Water: Nil	AR --Nil. Stack monitoring report dated 06-06-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes The unit has 1 D.G. Set(s) of 1000 KVA. Noise monitoring report dated 24-05-2016 issued by DPCC submitted. Report within Limit - Yes	12-07-2016 Redevelopment Area. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 The unit has submitted a letter on 04.10.2016 with a copy of the Rent agreement dated 07.10.2005 and an undertaking from the Landlord indicating that the premises was rented to M/s Advika Metals from 07.10.2005, as a proof for existence of the unit prior to date of MPD-2021 notification i.e. 7th February, 2007. As per the office order dated 20.05.2016, Undertaking from Landlord and copy Rent agreement is an acceptable document with regard to proof of Existence. However, the name of document is not listed in the minutes dated 02.08.2016. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 1. Online Monitoring system has been installed and provided User Name and Password to DPCC. 2.The unit has submitted Stack monitoring report dated 06-06-2016 issued by DPCC. As	04-11-2016 Consent to Operate granted for five years provided the fee is deposited within 15 days otherwise issue consent for one year.

per the Stack Test Report, parameters are within Limit.

3. A joint inspection was conducted by the Officials of Industries Department, Govt. of Delhi, SDM and DPCC to identify the existence of the unit within the boundaries of redevelopment Area. The team visited the redevelopment area to identify the above said unit namely M/s Advika Metals, Kh. No. 18/21, New Mandoli Ind. Area, New Delhi-110093 whose location on the app Maps. ME found between the latitude and longitude of 28.707926 degree N and 77.318247 degree E. The outer land mark was found electricity pole no. NNGX-609.

The member of Industry Department has confirmed that the unit is located within the boundaries of the redevelopment Area.

4. The unit has submitted a revised demand note from BSES Yamuna Power Ltd. in the name of Smt. Asha Gupta L/o Sh. Om prakash, Kh. 18/21, 12, 18/2, 19, 21/1, 22, 26, New Mandoli Ind. Area, New Delhi-110093, Pole No. 2349-2350 in application dated 12.01.2007 submitted to BSES Yamuna Power Ltd.. Wherein the unit has enclosed a rent agreement with landlady with the Advika Metal through its partner Sh. Himanshu Mittal s/o Sh. Suresh Kumar Mittal r/o of D-248, Vivek Vihar, Ph-1, Delhi-95 is of date 05.06.2014.

Recommendation / Action Taken Details (EE/AEE) on 20-09-

											2016 Case deferred decision in CMC meeting held on 12.07.2016	
10	SHAKTI SHYAM UDYOG	KH. N O-66, KRISHNA GALI NEW MANDOLI INDUSTRIAL AREA	11-05-2016	DPCC/EC/2/1/2016/14656	CASTING OF COPPER INGOT. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		A Notice u/s 21/22(A) of Air (Prevention & Control of Pollution) Act, 1981 and 25/26(A) of Water(Prevention & Control of Pollution) Act, 1974, was issued on 01.06.2015 for submission of application for CTE & CTO. As frequent complaints of Mandoli Industrial area for Air Pollution are being received, the file was processed for approval of Direction of Closure under u/s 31 (A) Air (Prevention & Control of Pollution) Act, 1981, as approved Closure Directions was issued to the unit on 28.08.2015. A representation was received from the unit on 09.10.2015 requesting for revocation of issued Closure directions by submitting that there unit is established prior to 7th Feb. 2007 and compliance of other directions. The inspection was carried out by DPCC officials on 11.12.2015 Direction of Closure under u/s 31 (A) Air (Prevention & Control of Pollution) Act, 1981, as approved Closure Directions was issued to the unit on 10.03.2016. A representation was received from the unit on 07.04.2016 requesting for revocation of issued Closure directions by submitting that there unit is established prior to 7th Feb. 2007 and compliance of other directions. Temporary Revocation of Direction of Closure for 10 days was issued on 10.06.2015 for unit only for the propose of removing the material lying. The unit has submitted compliance and also applied for CTO on 11.05.2016.	AR dated JAN 2016 issued by JAMIA MILLIA ISLAMIA submitted. Stack analysis report dated 08.10.2015 issued by DPCC submitted. Noise monitoring report of 62.5 KVA or 62.5 (not in use) dated 08.10.2015 issued by DPCC submitted and noise levels are within limit / beyond limit.	12-07-2016 Redevelopment Area. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 The file was put up administratively on 26.09.2016. In this case M/s ML Metal Industries was closed down and M/s Shakti Shyam Udyog was established at the same place with same activity.Further one of the partner is same/ Common in both the units. However documents submitted by the unit does not reveal that the previous unit was taken over by the new unit i.e M/s Shakti Shyam Udyog. The applicant has submitted a letter on 17.08.2016 wherein it has been requested to consider his unit in continuation of previous unit since the activity and premises is same as earlier, moreover one partner of new unit is also common. Chairman DPCC, directed to examine the case in light of recent guidelines on Redevelopment Areas. As per the document submitted, the unit may be treated as established after 07.02.2007. Recommendation / Action Taken Details (EE/AEE) on 21-07-2016 Redevelopment area case. However the unit was establish after 07th Feb. 2007, as previous unit	04-11-2016 Issue show cause notice for refusal of consent.

									(1)ETP ---- N/A (2)ECS - Wet Scrubber (3)D.G.Set Noise Report : 2 (4) water Consumption: 135 Liter/ Day, Source: out Source (5) Ground Water: Nil		operating at the same address was reportedly also having proprietorship by one of the partner of existing unit.	
11	CHEMISOFT TECHNOLOGIES PRIVATE LIMITED	127, POCKET L, SECTOR 5, DSIIDC, BAWANA INDUSTRIAL AREA, BAWANA,	18-05-2016		COSMETICS PRODUCTS Manufacturing of Kali Mehandi / Hair Colour in Powder form (Grinding and mixing only) Manufacturing of Soaps (without Trade Effluent) Manufacturing Of Toothpowder, Toothpaste, Talcum Powder And Other Cosmetic Items Manufacturing/formulation of Perfumery and Cosmetics (Not involved in the process - Production and /or industrial use of solvents and Production and/or industrial use of paints, pigments, lacquers ,varnishes, plastics and inks) Perfumes and Cosmetics Soap, Detergent Cake and Powder, Scouring Power and Bar (W/O Trade Effluent) Synthetic Soap (Formulation Only)	Orange Operate	Non-SPI		Status of Pollution Control system/Devices: 1. ETP- No 2. ECS- - 3. D.G. set- No Plot Area- 121.41 sq.mt. Proposed Date- 05.10.2010 Status of Ground Water Extraction:No 1. Water consumption: 500 L/day. a) Source of water: DJB Status of Inspection: No No hard copy submitted.	Water(Effluent)- - Air (Emission)- - Noise Test Report- -	06-07-2016 - Remarks / ATR on 03-11-2016 Show cause notice for refusal of consent issued on 10.10.2016. Hard copy for consent application is yet to be received. No reply received till date. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Letter issued on 25.07.2016 to submit hard copies of consent application along with required documents within 15 days. However, no reply received till date.	04-11-2016 Inspection be conducted.
12	AVON ALLOYS PVT LTD	B-8, JHILMIL INDUSTRIAL AREA	24-05-2016	DPCC/EC/2/1/2016/14790	MANUFACTURING OF ALUMINIUM INGOTS AND ALUMINIUM WIRE RODS (LESS THAN 25 MT/DAY) Aluminium Casting (except cupola furnace only), Rolling (with capacity less than 25 MT/day) and Annealing	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Wet Scrubber (3)D.G.Set Noise Report : 2 (4)Water Consumption:1000 L/d, Source: DJB (5) Groundwater :Nil	AR - requested. Stack analysis report dated - 08.02.2016 - issued by - DPCC Lab - submitted - Yes, analyzed parameter is within prescribed limit. The unit has 01 D.G. Set(s) of 82.5 KVA . Noise monitoring report dated 08-02-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes. number of parameters analyzed which are within prescribed limit. The unit has 01 D.G. Set(s) of 380 KVA. Noise monitoring report dated 08-02-2016 issued by DPCC submitted. Noise monitoring report within	12-07-2016 Recommended for CTO, followed by inspection. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 The inspection of the unit was conducted on 03.11.2016 and following were observed. 1. The unit was found operative. Preparation for casting of Aluminium wire rods was going on. 2. Although melting of Aluminium scrap/ingots was not going on in the furnaces(one horizontal rectangular	04-11-2016 Issue show cause notice for refusal of consent and show cause notice u/s 31(A) of Air Act.

										Limit - Yes, parameters analyzed which are within limit / beyond prescribed limit.	furnace and 4 circular vertical furnaces), but it has been found that the hood provided over vertical circular furnaces was not proper and effective. The hood is erected over the vertical furnace is common and extended to entire stretch where the shed circular furnaces installed in a line. Number of leakages were also found in the shed of hood. 3. The ECS that is cyclone separator followed by wet scrubber was found installed but it has been found that scrubbing capacity with respect to application of scrubbing effluent was seen very deficient. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection yet to be conducted.	
13	SYSTEM INDIA PVT LTD	KH. NO.111/7, MUNDKA INDUSTRIAL AREA	25-05-2016	DPCC/EC/2/1/2016/14806	MFG. OF ALUMINIUM PRESSURE DIE CASTING WITH POWDER COATING (DRY). Aluminium Pressure Die Casting Powder Coating without phosphating	Orange Operate	Non-SPI		Water Consumption-500 Litres/ Day (copy of bill provided) Source of Water- Outside Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP ---- N/A (2)ECS - Cyclone (3)D.G.Set Noise Report : 1 D.G. Set(s) of 62 KVA Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	Air Emission- - Stack monitoring report dated 24-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Stack Test Report within Limit - Yes -Stack monitoring report dated 24-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Stack Test Report within Limit - Yes Noise- The unit has 1 D.G. Set(s) of 62 KVA. Noise monitoring report dated 15-03-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise monitoring report within Limit - No	11-07-2016 . Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 -As decided, a letter regarding submitting certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit issued to the unit on 05.10.2016. Recommendation / Action Taken Details (EE/AEE) on 22-09-2016 Case may be decided as per the decision taken w.r.t. redevelopment area policy	04-11-2016 Issue show cause notice for refusal of consent.
14	NITIN OVERSEAS	A-63, WAZIRPUR INDUSTRIAL AREA	30-05-2016	DPCC/EC/2/1/2016/14866	MFG. OF UTENSILS WITH BUFFING AND COLD RE-ROLLING. Cold Re-Rolling without Pickling of S .S. Sheets (with capacity less than 25 MT/ day)	Orange Renewal	Non-SPI		Status of Pollution Control System (1)ETP ---- N/A (2)ECS - Cyclone Stack monitoring report	Stack monitoring report dated 10-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Stack Test Report within Limit - Yes	11-07-2016 . Recommendation / Action Taken Details (EE/AEE) on 02-11-	04-11-2016 Expedite inspection.

					Manufacturing of Stainless Steel Utensils (with Buffing Activity)				dated 10-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Stack Test Report within Limit - Yes (3)D.G.Set: ...Nil Status of Ground Water extraction : Nil Source of Water: 0.1 KLD from DJB (bill enclosed) Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No		2016 Inspection yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 21-07-2016 This case again deferred in the meeting dated 18.07.2016.	
15	M. M. ENTERPRISES	15/5 MANDOLI INDUSTRIAL AREA	01-06-2016	DPCC/EC/2/1/2016/14902	CASTING OF FERROUS / NON FERROUS METAL (EXCEPT CUPOLA FURNACE ONLY). Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Wet Scrubber (3)D.G.Set Noise Report : 1 (4) Water Consumption: 200 L/ Day Source: Out Source (5) Ground Water: Nil	AR- Nil Stack monitoring report dated 25-04-2016 issued by DPCC submitted, the analysed parameter are within the prescribed limit The unit has 1 D.G. Set(s) of 25 KVA. Noise monitoring report dated 12-04-2016 issued by DPCC submitted the analysed parameter is within the prescribed limit.	12-07-2016 Redevelopment Area case for CTO. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Letter has been issued to the unit on 03.11.2016 for submitting the certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit and for installation of online monitoring system. Inspection yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 21-07-2016 Redevelopment Area Case.	04-11-2016 Expedite inspection.
16	GREEN LOUNGE NORTH BANQUETS (A UNIT OF NAGPAL HOSPITALITY PVT. LTD)	C-03, GROUND FLOOR, 1ST FLOOR WAZIR PUR INDUSTRIAL AREA	03-06-2016	DPCC/EC/2/1/2016/14934	BANQUETS. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal /	Orange Operate	Non-SPI		Status of Pollution Control System (1)ETP Effluent analysis report dated 05-04-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes (2)ECS - N/A (3)D.G.Set Noise Report : 2	1. Effluent analysis report dated 05-04-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes 2. Noise monitoring reports dated 08-04-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	18-07-2016 Unit has also submitted valid MCD Licence and requested to correct the address from C-03 to C-93. Recommendation / Action Taken Details (EE/AEE) on 02-11-2016 As decided, the unit	04-11-2016 Consent to Operate granted.

					DJB Sewer and having Kitchen and / or Laundry without Boiler				(a) The unit has 2 D.G. Set(s) of 250 KVA and 250 KVA. Noise monitoring reports dated 08-04-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes Status of Ground Water extraction :Nil Source of Water: 4.0 KLD from DJB (bill enclosed)		was inspected on 07.10.2016 and following were observed: -The unit has installed an ETP (batch type) which was found in operational condition. -The unit has provided Channelization system followed by a duct above roof level in both the kitchens. -Acoustic enclosure and adequate stack height has been provided with both the D.G. sets. -The unit is having two borewells, however no permission from DJB/CGWA was shown. As per decision taken on file, a letter to DC (North West) for necessary action w.r.t extraction of groundwater is to be issued.	
17	SEVEN STAR HOTEL AND RESORTS PVT. LTD.	MAIN GT KARNAL ROAD, VILLAGE KHAMPUR, OPP. RADIO STATION	06-06-2016	DPCC/EC/2/1/2016/14943	MOTELS (NO. OF ROOMS 18). Hotel/ Guest Houses having less than 20 rooms (double bed) or 40 rooms (single bed) (excluding 3 Star and above) - not connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Operate	Non-SPI		Status of Pollution Control system/Devices: 1. STP- Yes (50 KLD) 2. ECS- No 3. D.G. set- Yes, 1x 250 KVA Plot Area- 20841 sq.mt. Proposed Date- 01.06.2015 Status of Ground Water Extraction:No 1. Water consumption: 35000 L/day. a) Source of water: Outside (copy of Outside water bill not submitted) Status of Inspection: No MCD building plan & completion certificate submitted. Receipt for MCD license submitted.Area is unsevered and parameter phosphate is not measured.	Effluent analysis report of STP dated 30.12.2015 issued by DPCC submitted. Parameters are within prescribed limit.However parameter phosphate is not measured. Air (Emission)-N/A Noise monitoring report dated 13.01.2016 issued by Center for Occupational and Environmental Health(IVPSS) submitted. Parameters are within prescribed limit.	06-07-2016 - Remarks/ATR on 03-11-2016 Letter issued on 25.07.2016 to submit fresh effluent analysis report of ETP from em-panelled laboratory of DPCC. Unit has submitted reply on 01.09.2016 along with fresh effluent analysis report dated 30.08.2016 issued by DPCC. Parameters are within prescribed limit. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Letter issued on 25.07.2016 to submit fresh complete effluent analysis report of ETP from empanelled laboratory of DPCC. Unit replied on 01.09.2016 wherein	04-11-2016 Consent to Operate granted.

											submitting effluent analysis report on 30.08.2016 issued by DPCC. Parameters are within prescribed limit.	
18	THE JRD LUXURY BOUTIQUE HOTEL (A UNIT OF JRD BUILDCON PVT. LTD.)	B-7/113A SAFDARJUNG ENCLAVE	06-06-2016	DPCC/EC/2/1/2016/14944	GUEST HOUSE. Hotel/ Guest Houses having more than 50 rooms (double bed) or 100 rooms (single bed) (excluding 3 Star and above) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry with Boiler	Orange Operate	Non-SPI		Source of Water- Delhi Jal Board (Cat-II) & Outside (Copy of bill DJB provided but not for outside purchase water bill) Water Consumption-10320 Litre/Day Ground Water- Nil Status of Pollution Control System (1)ETP ---- Working (2)ECS - One diesel fired boiler capacity of 2500 Litre/Hour with stack height above roof level 4metre. (3)D.G.Set: . 1 D.G Set of 125 KVA (with acoustic enclosure provided) (4) Inspection details:No (5) SCN u/s 31(A)/33(A)/5 of EPA details : No (6) Closure directions u/s 31(A)/33(A)/5 of EPA details : No	Water Effluent- Effluent analysis report dated 11-05-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes Air Emission- Stack monitoring report dated 19-05-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes Noise- The unit has 1 D.G. Set(s) of 125 KVA. Noise monitoring report dated 06-04-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	06-07-2016 . Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 An inspection was carried out by DPCC officials on 03.11.2016 and following observations were made: -During inspection unit found operational and engaged in the activity of Hotels. -ETP installed in the premises found functional. -Channelization provided in kitchen with adequate stack height. -Log book of the ETP maintained. -One DG Set of capacity 125 KVA installed at roof building with adequate stack.	04-11-2016 Consent to Operate granted.
19	PEARL GRAND GALAXY (A UNIT OF BLACK PEPPER HOSPITALITY)	PLOT NO. - 3, EAST GURU ANGAD NAGAR	09-06-2016	DPCC/EC/2/1/2016/15040	BANQUET HALL. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Operate	Non-SPI		(1)ETP ---- STP (2)ECS - N/A (3)D.G.Set Noise Report : 2 (4) Water Consumption: 19000 L/ Day Source: Outside (5) Ground Water: Nil	AR Nil Effluent analysis report dated 05-04-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes, number of parameters analyzed which are within limit. The unit has 2 D.G. Set(s) of 500 KVA and 500 KVA. Noise monitoring report dated 22-03-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes number of parameters analyzed which are within limit. The unit has 2 D.G. Set(s) of 500 KVA and 500 KVA. Noise monitoring report dated 22-03-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes number of parameters analyzed which are within limit.	12-07-2016 CTE has been granted with the condition to submit the proof i.e. water is being obtained from the authorized source and copy of valid MCD licence. If the unit submit the required documents than CTO be granted. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Inspection of the unit was conducted on 03.11.2016 and following were observed. 1. The unit was found in operation condition although no function was going on during the inspection. 2. ETP was found installed however modification work that is conversion of	04-11-2016 Issue show cause notice for refusal of consent and show cause notice u/s 33 (A) of Water Act.

											biological treatment to Physio chemical treatment was going on. 3. At present it was informed that as in past few functions were carried out and as holding capacity of collection tank good enough to hold the trade effluent upto 60 KLD. So the effluent is collected in the holding tank at present.	
20	RIDERS CORNER	B-48, KESHOPUR INDUSTRIAL AREA	27-06-2016	DPCC/EC/2/1/2016/15211	SERVICING, REPAIRING AND WASHING OF TWO WHEELERS. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 27-06-2016 Authorisation Status Pending	Spurce of Water: outside (copy of bill not provided) Water Consumption: 1100 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP ---- Other ETP Name : ETP (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	Effluent: Effluent analysis report dated 30.12.2015 issued by Water Lab, DPCC submitted. parameters found within limit-yes	21-07-2016 Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 As decided,a show cause notice for refusal of consent & authorization and show cause notice u/s 33(A) of Water Act & u/s 5 of EP Act was issued to the unit on 05.10.2016. Recommendation / Action Taken Details (EE/AEE) on 19-09-2016 -As decided, an inspection was carried out by DPCC officials on 16.09.2016 and following observations were made: -ETP found installed but no proper dosing observed in dosing tank and hence waste water is not treating properly. -Hazardous waste management guidelines not being followed. -Used oil containers being stored outside in an open area. -No log book shown. -No documentary proof shown for selling used oil to authorized dealer.	04-11-2016 Consent refused. File be put up administratively for further necessary action.
21	KNITCRAFT APPARELS INTERNATIONAL PVT. LTD.	A-81, PHASE-I, NARAINA INDUSTRIAL AREA	28-06-2016	DPCC/EC/2/1/2016/15270	MFG. OF READYMADE GARMENTS (WITH WASHING).	Orange Renewal	Non-SPI	HWM Application No. 1	Source of Water: DJB (CAT-II) name not matched and address matched	Effluent: (b) Effluent analysis report dated 02-05-2016 issued by FICCI	21-07-2016 Noise monitoring report fails to meet the prescribed	04-11-2016 Reply awaited so case deferred.

					Readymade Garment (with Washing) with Boiler				Application Date 25-05-2009 Authorisation Status Pending	Water Consumption: 500 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP - Working (2)ECS - Working (3)D.G.Set Noise Report : 1 D.G. Set(s) of 125 KVA Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	RESEARCH ANALYSIS CENTRE submitted. Effluent Test Report within Limit - Yes Emission: -Stack monitoring report dated 23-04-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Stack Test Report within Limit - Yes -Stack monitoring report dated 23-04-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Stack Test Report within Limit - Yes Noise: (a) The unit has 1 D.G. Set(s) of 125 KVA. Noise monitoring report dated 23-04-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise monitoring report within Limit - No	standard. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 -As deiced a letter regarding submission of fresh noise monitoring report was issued to the unit on 03.11.2016. Recommendation / Action Taken Details (EE/AEE) on 21-09-2016 -A letter yet to be issued regarding submission of fresh noise monitoring report.	
22	ASHOK GUPTA	422-F, PLOT NO 19, GALI NO 7, FRIENDS COLONY INDUSTRIAL AREA	29-06-2016	DPCC/EC/2/1/2016/15287	MFG./ASSEMBLING OF BATHROOM FITTINGS WITH MACHINING AND BUFFING W/O(CASTING,GRINDING AND ELECTROPLATING) Process Involving Buffing	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Dust Collector (3)D.G.Set: ...N/A... (4) Water Consumption: 100 L/ Day, Source: DJB (5) Ground Water: Nil	AR : Nil Stack monitoring report dated 01-06-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Stack Test Report within Limit - Yes number of parameters analyzed which are within prescribed limit.	20-07-2016 Recommended for CTE. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Inspection of the unit was conducted on 17.10.2016 and following were observed: 1. No Electroplating work facility exists. 2. The portion at 2nd floor where electroplating work reportedly being carried out found vacant. No machine etc were found installed. No casting facility exists. 3. At present the unit was found doing machining, grinding, & buffing on the sanitary fittings at basement both side buffing and grinding exists and at 1st floor machining and packing being carried out. 4. The unit is having suction and hood arrangement and dust collector system.	04-11-2016 Consent to Operate granted.	

											Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection yet to be conducted.	
23	VIKASH DHATU UDYOG	B-15/5, SHAHDARA, JHILMIL INDUSTRIAL AREA	29-06-2016	DPCC/EC/2/1/2016/15299	COPPER WIRE DRAWING WITH SUPER ENAMELING Copper Wire Drawing with Super Enamelling (Dry Process)	Orange Renewal	Non-SPI	HWM Application No. 1 Application Date 28-09-2006 Authorisation Status Pending HWM Application No. 2 Application Date 29-06-2016 Authorisation Status Pending	(1)ETP ---- N/A (2)ECS - Catalytic Converter (3)D.G.Set: ...N/A... (4) Water Consumption: 100 L/ Day, Source: DJB (5) Ground Water: Nil	AR : N/A Stack monitoring report dated 29-06-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes number of parameters analyzed which are within prescribed limit.	20-07-2016 Recommended for Inspection. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Inspection of the unit was conducted on 06.10.2016 and following was observed: 1. The unit was found in operation having vertical Super Enameling machine of 40 feet high with 12 lines with catalytic Converter. 2. A D.G Set of 82.5 K.V.A found installed in acoustic enclosure with stack of about 30 feet from Ground Level but found non-working condition. 3.The unit has not taken measures for Hazardous waste Management. As informed after over hauling and regular residue of super enameled waste dumped to nearby dustbin. Recommendation: Recommended to issue Show Cause notice u/s 5 of EPA Act for non compliance of Hazardous waste management Rules. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection yet to be conducted.	04-11-2016 Issue Show Cause notice for refusal of consent / authorization and show cause notice u/s 5 of EPA Act for non compliance of Hazardous waste management Rules.
24	M/S KHANDELWAL AUTOMOBILES	PLOT NO.150, PATPARGANJ INDUSTRIAL AREA, NEW DELHI-110092	30-06-2016	DPCC/EC/2/1/2016/15318	AUTOMOBILE WORKSHOP WITH WASHING. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 30-06-2016	inspection was carried out by DPCC officials on 07.12.2015 and for the deficiencies a Notice u/s 33(A) of Water (Prevention & Control of	(a) Effluent analysis report dated 27-06-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes, number of parameters	20-07-2016 Recommended for Inspection. Remarks/ATR on	04-11-2016 Consent to Operate and Authorization under HWM Rules granted.

[illegible]

											plastic drum being used as Hazardous waste storage container. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection yet to be conducted.	
25	CHEMO DRUGS AND CHEMO REMEDIES	A-50, G.T. KARNAL ROAD INDUSTRIAL AREA	30-06-2016	DPCC/EC/2/1/2016/15329	MANUFACTURING OF PHARAMACEUTICAL FORMULATION. Pharmaceuticals Formulation With Washing Operation	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 08-07-2004 Authorisation Status Approved Authorisation Issue Date 04-08-2004 Authorisation Expiry Date 03-08-2006 HWM Application No. 2 Application Date 06-10-2006 Authorisation Status Pending HWM Application No. 3 Application Date 30-06-2016 Authorisation Status Pending	Status of Pollution Control system/Devices: 1. ETP- Yes 2. ECS- N/A 3. D.G. set- No Plot Area- 334.45 sq mt Date commencement- 01.04.1996 Status of Ground Water Extraction: No 1. Water consumption: 400 L/day. a) Source of water: Corporation (copy of Corporation water bill submitted) Status of Inspection: No Unit has submitted Form-I under HWM rules.	Effluent analysis report dated 29.06.2016 issued by DPCC Submitted.Parameters are within prescribed limit. Air (Emission)-N/A Noise Test Report- No	20-07-2016 - Remarks/ATR on 04-11-2016 Show cause notice for refusal of authorisation and show cause notice u/s 5 of EPA Act issued on 10.10.2016. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection conducted on 16.09.2016. Inspection findings are as follows- 1. Unit found operating and engaged in the activity of Mfg. of Pharmaceuticals formulation. 2. ETP found installed and in operation. 3. HWM rules are not complied with except providing display board. Remarks/ATR on 30-08-2016 -	04-11-2016 Reply awaited so case deferred.
26	UTILITY FORMS PVT. LTD.	A-24/B-1, MOHAN CO-OPERATIVE INDUSTRIAL ESTATE	30-06-2016	DPCC/EC/2/1/2016/15357	OFFSET PRINTING WITH WASHING. Printing with Trade Effluent Discharge	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 30-06-2016 Authorisation Status Pending	Status of Pollution Control System (1)ETP -Yes (a) Effluent analysis report dated 21-06-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes (2)ECS - N/A (3)D.G.Set: N/A Status of Ground Water extraction : Nil Water Consumption- 770 ltrs/day, Source-	(a) Effluent analysis report dated 21-06-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes	30-08-2016 Unit has applied for CTE and CTO on 30.06.2016 and also applied for HMW Authorization on 30.06.2016. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Inspection is yet to be conducted. Recommendation / Action Taken Details	04-11-2016 Expedite inspection.

									Outsource		(EE/AEE) on 21-09-2016 Inspection is yet to be conducted.	
									The pictures enclosed with the application of Consent to Operate depict that the ETP is of M/s Utility Forms Pvt Ltd located in the adjacent building with address A-23/B-1, Mohan Co-operative Industrial Estate. Inspection is to be carried out in Utility Forms Pvt Ltd, A-23/B-1, Mohan Co-operative Industrial Estate as per the decision of Competent Authority.			
27	RAJINDER SERVICE STATION	2, SHAM NATH MARG	30-06-2016	DPCC/EC/2/1/2016/15379	PETROL PUMP CUM SERVICE STATION OF CARS. Automobile Fuel Outlet (with Automobile Servicing, Washing, Repairing and Painting)	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 30-06-2016 Authorisation Status Pending	Status of Pollution Control system/Devices: 1. ETP- Yes(Oil and Grease trap) 2. ECS- N/A 3. D.G. set- 1x82.5 KVA Plot Area- 1124.12 sq mt Date of commencement- 01.01.1976 Status of Ground Water Extraction: No 1. Water consumption: 3000 L/day. a) Source of water: DJB (copy of DJB water bill submitted) Status of Inspection: No Unit has submitted Form-I under HWM rules. Unit has applied online and not submitted the following documents: (i)Sanctioned building plan(DDA/MCD) (ii) Approved layout plan (DDA/MCD) (iii) Allotment letter/dealership agreement is valid as on date (iv) Letter from oil company that dealership agreement is valid as on date (v) Authority letter, in original, regarding filling/signing of consent/authorization application. Unit has applied online under HWM and not submitted the following documents: (i) Photograph of container for storage of hazardous waste. (ii) Photograph of display boards.	Effluent analysis report of outlet of ETP (Automobile fuel outlet) dated 30.06.2016 issued by DPCC Submitted.Parameters are within prescribed limit. Air (Emission)-N/A Noise monitoring report dated 30.06.2016 issued by DPCC submitted.	20-07-2016 - Remarks/ATR on 04-11-2016 Letter issued on 21.09.2016 to submit the deficient documents mentioned in the receipt of CTE application within 15 days. No reply received till date. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection is yet to be conducted. Remarks/ATR on 30-08-2016 -	04-11-2016 Expedite inspection. Issue reminder.
28	R.L. PLASTICS INDUSTRIES	PLOT NO-240, SECTOR-5, POCKET-M, DSIIDC BAWANA INDUSTRIAL AREA	01-07-2016	DPCC/EC/2/1/2016/15387	Mfg. of Secondary Plastic Dana With Washing. Reprocessing of Waste Plastic / PVC (with Washing Activity)	Orange Operate	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- Yes 2. ECS- Yes, Attached to Suction hood 3. D.G. set- No Plot Area- 250 sq mt Date of establishment- 01.09.2015 Status of Ground Water	Effluent analysis report - dated 19.05.2016 from FICCI submitted. Parameters are within prescribed limit. Stack moniotring report dated 18.05.2016 from FICCI submitted. Parameters are within	27-09-2016 . Remarks/ATR on 03-11-2016 Letter issued on 24.10.2016 giving 30 days time to the unit to apply for fresh	04-11-2016 Reply awaited so case deferred. Inspection be conducted.

Extraction-No 1. Water consumption-850 L/day. a) Source of water-DSIIDC (copy of DSIIDC water bill submitted) Status of Inspection- No Form 2 for registration under plastic rules submitted. Form 2 found incomplete and not as per the prescribed performance as per new Plastic rules 2016. As per Rule 13 (Registration of producer, recyclers and manufacturer) of Plastic rules 2016, further sub-rule (5) says that The State Pollution Control Board or the Pollution Control Committee shall not issue or renew registration to plastic waste recycling or processing units unless the unit possesses a valid consent under the Water (Prevention and Control of Pollution) Act, 1974 (6 of 1974) and the Air (Prevention and Control of Pollution) Act, 1981 (14 of 1981) along with a certificate of registration issued by the District Industries Centre or any other Government agency authorised in this regard. sub-rule (7) says that On receipt of the application complete in all respects for the registration for recycling or processing of plastic waste under sub-rule (3), the State Pollution Control Board may, after such inquiry as it considers necessary and on being satisfied that the applicant possesses appropriate facilities, technical capabilities and equipment to handle plastic waste safely, may grant registration to the applicant on fulfilment of the conditions as may be laid down in terms of registration. sub-rule (8) says that Every State Pollution Control Board or Pollution Control Committee shall take a decision on the grant of registration within ninety days of receipt of an application which is complete in all respects. sub-rule (9) says that The registration granted under	prescribed limit. Noise monitoring report - N/A	authorisation under Plastic Waste Rule, 2016 along with certificate of registration issued by Industries Department. Reply is yet to be received.
--	--	---

									this rule shall initially be valid for a period of one year, unless revoked, suspended or cancelled and shall subsequently be granted for three years.			
29	GARG DISTRIBUTORS	D-16/4, PHASE-I, OKHLA INDUSTRIAL AREA	08-07-2016	DPCC/EC/2/1/2016/15425	Automobile workshop for Servicing and Repair with washing of two wheelers. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 08-07-2016 Authorisation Status Pending	Status of Pollution Control System (1)ETP ---- Other ETP Name : ETP (a) Effluent analysis report dated 11-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Effluent Test Report within Limit - Yes (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Ground Water extraction : Nil Water Consumption- 800 ltrs/day, Source- DJB (bill enclosed)	Effluent analysis report dated 11-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Effluent Test Report within Limit - Yes	21-07-2016 Unit has also applied for Authorization under HWM Rules on 08.07.2016 Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 As decided by the Committee an inspection of unit was carried out by Official / Representative of DPCC on 26.09.2016. During the inspection following were observed- - Unit found in operation for the activity of Automobile Workshop for Servicing & Repair with Washing of two Wheelers. - Unit has installed an ETP and same found non-operational. - Wet / Dry sludge (ETP sludge) not available at site. - Logbook of ETP not maintained. - Record of hazardous waste not maintained. - Unit is not complying with the provisions of Hazardous Waste Management Rules. As decided, Show Cause Notice u/s 33(A) of Water Act & u/s 5 of Environment (Protection) Act, 1986 and Show Cause Notice for Refusal of Consent to Operate under Air & Water Acts and Show Cause Notice for Refusal of Authorization under Hazardous & Other Wastes (Management and Transboundary Movement) Rules, 2016 issued to unit on 06.10.2016 w.r.t. deficiencies observed during inspection.	04-11-2016 Take action as per decision in file.

											Unit has submitted reply on 27.10.2016 w.r.t. Show Cause Notice informing that their ETP is operational, on the day of inspection one motor pump was not working that has been repaired, in-charge person not available so that wet / dry sludge not shown, logbook of ETP & record of hazardous waste maintained, display board provided, hazardous waste is stored in leak proof container marked with specified label with beginning date, kept in isolated & covered area on pucca floor. The unit has requested to with draw the notice.	
30	AUTOWISE SERVICE STATION	PP-38A, GALI NO. 10, ANAND PARBAT INDUSTRIAL AREA	13-07-2016	DPCC/EC/2/1/2016/15448	Servicing of Vehicles (with Washing) Automobile Servicing and Repair Station with Washing Activity	Orange Renewal	Non-SPI	HWM Application No. 1 Application Date 19-01-2004 Authorisation Status Approved Authorisation Issue Date 16-07-2004 Authorisation Expiry Date 15-07-2006 HWM Application No. 2 Application Date 21-07-2006 Authorisation Status Pending HWM Application No. 3 Application Date 16-07-2014 Authorisation Status Approved Authorisation Issue Date 19-02-2015 Authorisation Expiry Date 15-07-2019	Source of Water: Tanker (copy of bill provided) Water Consumption: 300Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP - Working (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	Water Effluent: Effluent analysis report dated 17-06-2016 issued by SHRIRAM INSTITUTE submitted. Effluent Test Report within Limit - No .	30-08-2016 . Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 -Unit submit its reply on 26.09.2016 along with the copy of log book of ETP, copy of authorization certificate for used oil and photographs of Hazardous waste storage room also provided. -A letter regarding submitting fresh effluent analysis report of ETP with complete parameters including TSS issued to the unit on 03.11.2016. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 As per decision in cmc meeting held on 31.08.2016 headed by MS,DPCC an inspection of the unit has been carried out by DPCC Official on 22.09.2016 during inspection following observations were made:	04-11-2016 Reply awaited so case deferred.

								HWM Application No. 4 Application Date 13-07-2016 Authorisation Status Pending			- ETP found installed and same found operational. - No ETP log book shown. -Authorization for used oil not shown. -Hazardous waste management rules not being complied. -Show cause notice under section 5 of Environment (Protection) Act may	
31	RAJPOOT MOTORS	C-9, S.M.A COOPERATIVE INDUSTRIAL ESTATE , G.T. KARNAL ROAD	19-07-2016	DPCC/EC/2/1/2016/15533	Two Wheelers workshop (Washing and repairing) Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 19-07-2016 Authorisation Status Pending	Status of Pollution Control system/Devices- 1. ETP-Yes 2. ECS- No 3. D.G. set- N/A Plot Area- 350 sq.mt. Commencement Date- 01.03.2016 Status of Ground Water Extraction-No 1. Water consumption- 170 L/day. a) Source of water- Outside (copy of outside water bill submitted) Status of Inspection- No	Water(Effluent)-report issued by FICCI on 27.05.2016. Parameters are within prescribed limit. Air(Emission) -No Noise Test Report- N/A	30-08-2016 - Remarks /ATR on 04-11-2016 Show cause notice for refusal of consent and authorisation, Show cause notice u/s 33(A) of Water Act and u/s 5 of EPA for closure of the unit issued on 28.10.2016 Recommendation / Action Taken Details (EE/AEE) on 27-09-2016 Inspection conducted on 16.09.2016. Inspection findings are as follows- 1. Unit found operating and engaged in the activity of repairing & washing of two-wheelers. 2. ETP found installed but not in operation. Waste water is being discharged into sewer without any treatment. 3. HWM rules are not complied with.	04-11-2016 Reply awaited so case deferred.
32	RAWAT MOTORS	D-192, PEERAGARHI CHOWK	20-07-2016	DPCC/EC/2/1/2016/15537	SERVICING AND REPAIRING CENTRE OF AUTOMOBILES. Automobile Servicing and Repair Station with Washing Activity with burner	Orange Renewal	Non-SPI	HWM Application No. 1 Application Date 29-10-2013 Authorisation Status Approved Authorisation Issue Date 19-05-2015 Authorisation Expiry Date 07-04-2016 HWM	Source of Water: Tanker (copy of bill not provided) Water Consumption: 1300 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP ---- N/A (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Inspection : No SCN u/s 31(A)/33(A)/5 of	Water Effluent- Effluent analysis report dated 27-06-2016 issued by SHRIRAM INSTITUTE submitted. Effluent Test Report within Limit - Yes Air Emission- Stack monitoring report dated 16-06-2016 issued by SHRIRAM INSTITUTE submitted. Stack Test Report within Limit - Yes	30-08-2016 . Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Unit submit its reply on 13.10.2016 along with the copy of log book, copy of authorisation to sold out used oil with bill, photographs of storage room and display board also board. Also, stated that all the	04-11-2016 Inspection be conducted.

								Application No. 2 Application Date 20-07-2016 Authorisation Status Pending	EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No		deficiencies have been rectified. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 As per decision in cmc meeting held on 31.08.2016 headed by MS,DPCC an inspection of the unit has been carried out by DPCC Official on 22.09.2016 during inspection following observations were made: - ETP installed and found operational. - No log book shown during inspection. -Authorization for used oil not shown. -Paint booth installed at third floor of the building & same was found with adequate stack height. -No wet and dry sludge observed, as informed they through out the waste outside the premises. -Show cause notice u/s 5 of Environment (Protection) Act may be issued to the unit.	
33	GLOBAL WASH	C-211, SECTOR-1, DSIIDC, BAWANA INDUSTRIAL AREA	25-07-2016	DPCC/EC/2/1/2016/15586	JOB WORK OF WASHING OF READYMADE GARMENTS (WITH OIL FIRED BOILER). Readymade Garment (with Washing) with Boiler	Orange Operate	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- Yes 2. ECS- Yes 3. D.G. set- Yes, 125 KVA Status of Ground Water Extraction-Yes 1. Water consumption- 15000 L/day. a) Source of water- Ground water/Outside source (copy of Outside source bill not submitted) Status of Inspection- Yes Inspection was conducted on 22.09.2015 by the officials of DPCC and inspection findings are as follows Unit found operating and engaged in the activity of jeans dyeing, No valid consent from DPCC, ETP under installation, waste water discharges directly into the sewer without treatment, One boiler (horizontal) (one tonne/hr) found in use	Water(Effluent)-report for readymade garment washing issued by FICCI on 16.06.2016 submitted meeting the prescribed limit. Emission monitoring report - report issued by FICCI on 09.06.2016 submitted. Parameters are within prescribed limit. Noise Test Report- report issued by FICCI on 25.06.2016 submitted. Parameters are within prescribed limit.	30-08-2016 - Remarks/ATR on 03-11-2016 To comply with the decision of consent committee file is put up administratively and same is under submission. Reply received from the unit on 13.10.2016 wherein it is submitted that dyeing work is completely closed and only Job work of washing of readymade garments is going on. The unit has also stated that it has installed ETP (Photograph enclosed) and Coal fired boiler is converted into oil fired boiler	04-11-2016 Take action as per decision in file.

									and coal is used as fuel causing air pollution. No ECS installed, HWM rules are not complied with, One Borewell exists without permission from DJB.		(Photograph enclosed). Remarks/ATR on 29-09-2016 Inspection conducted on 28.09.2016. Inspection findings are as follows- 1. Unit found in operation and engaged in the activity of Washing of Jeans. 2. ETP found installed and in working condition. 3. Diesel fired boiler found under installation. 4. Coal is being used in the boiler at present. Recommendation / Action Taken Details (EE/AEE) on 27-09-2016 Inspection is yet to be conducted.	
34	A.R. STAMPINGS	C-5, MANDOLI INDUSTRIAL AREA, PHASE-I, NEAR SHIVANI DHARAM KANTA	25-07-2016	DPCC/EC/2/1/2016/15596	MFG.OF ELECTRICAL STAMPING (CORE) WITH ALUMINIUM METAL CASTING BY PIT FURNACE. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Suction hood with stack on Pit furnace (3)D.G.Set Noise Report : N/A (4) Water Consumption: 160 L/ Day Source: Tanker (5) Ground Water: Nil	Stack monitoring report dated 02-06-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Stack Test Report within Limit - Yes. One number of parameters analyzed which are within prescribed limit.	30-08-2016 Re-development area. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Letter has been issued to the unit on 04.11.2016 for submitting the certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit and for installation of online monitoring system. Inspection yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 The file from the record has been obtained which indicated that the unit has submitted proof of existence (i.e.	04-11-2016 Expedite inspection.

											Electricity Bill dated 25.03.2006, VAT Tax dated 13.12.2005 etc.) prior to 07.02.2007.	
35	VAIBHAV STRIPS PVT. LTD.	KHASRA NO 12/8, NEW MANDOLI INDUSTRIAL AREA	28-07-2016	DPCC/EC/2/1/2016/15615	MANUFACTURING OF ALUMINIUM WIRE ROD Copper / Aluminium Re-Rolling Industry(Foils and Strips Etc.) with Capacity less than 25MT/Day	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Scrubber, Cyclone (3)D.G.Set Noise Report : 1 (4) Water Consumption: 100 L/ Day Source: Outside Water (5) Ground Water: Nil	Stack monitoring report dated 29-06-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes. One number of parameters analyzed which are within prescribed limit. The unit has 3 D.G. Set(s) of 380 KVA(non operational),250 KVA(not in use)and 100 KVA. Noise monitoring report dated 18-07-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes number of parameters analyzed which are within prescribed limit.	30-08-2016 Redevelopment Area Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Letter has been issued to the unit on 03.11.2016 for submitting the certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit and for installation of online monitoring system. Inspection yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 Unit has submitted copy of allotment of Tax Payers Identification Number (TIN) signed on 07.03.2015 as a proof of its respective date of establishment prior to the notification of MPD-2021 i.e. 07.02.2007. Unit has also submitted electricity Bill wherein Enengisation date 30.07.2007.	04-11-2016 Expedite inspection.
36	SHIVHEM	G-5, NEW MANDOLI INDUSTRIAL AREA, MANDOLI	28-07-2016	DPCC/EC/2/1/2016/15618	IRON STRIP MANUFACTURER. Stainless Steel Rerolling (Hot) (with capacity less than 25 MT/ day)	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Scrubber, Scrubber (3)D.G.Set ---- N/A (4) water Consumption: 200 Liters/Day Source: Outside (5) Ground Water: Nil	AR: Nil Stack monitoring report dated 31-05-2016 issued by SHRIRAM INSTITUTE submitted. Stack Test Report within Limit - No number of parameters analyzed which are within limit / beyond prescribed limit. Stack monitoring report dated 31-05-2016 issued by SHRIRAM INSTITUTE submitted. Stack Test Report within Limit - Yes	26-09-2016 As decided in the CMC meeting of II(b) category held on 06.09.2016, unit may be asked to submit certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit including	04-11-2016 Issue show cause notice for refusal of consent. Also inspection be conducted.

										number of parameters analyzed which are within limit / beyond prescribed limit.	other deficiencies in respect of the consent application, if any, submitted by the unit. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 The unit has submitted copy of MCD license dated 28.06.1995 as proof of establishment before 07.02.2007. Stack monitoring report dated 31-05-2016 issued by SHRIRAM INSTITUTE submitted. Stack Test Report within Limit - Yes The unit has not installed online monitoring system. As per the decision taken on 30.09.2016 unit may be asked to submit certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit including other deficiencies in respect of the consent application.	
37	METRO TRANSIT PRIVATE LIMITED	CLUSTER BUS DEPOT, VILLAGE- KAIR, NEAR GOVERNMENT COLLEGE	29-07-2016	DPCC/EC/2/1/2016/15636	BUS REPAIR AND MAINTENANCE WASHING PARKING. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 29-07-2016 Authorisation Status Pending	Status of Pollution Control System (1)ETP - Yes (a) Effluent analysis report dated 16-06-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Effluent Test Report within Limit - Yes (2)ECS - N/A (3)D.G.Set- Yes (a) The unit has 1 D.G. Set(s) of 125 KVA. Noise monitoring report dated 13-06-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise	Effluent analysis report dated 16-06-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Effluent Test Report within Limit - Yes The unit has 1 D.G. Set(s) of 125 KVA. Noise monitoring report dated 13-06-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise monitoring report within Limit - Yes	30-08-2016 Unit has also applied for Authorization under HWM Rules on 29.07.2016. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Inspection is yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 29-09-2016 Inspection is yet to be conducted.	04-11-2016 Expedite inspection.

									monitoring report within Limit - Yes			
									Status of Ground Water extraction : Nil Water Consumption- 11000 liters/ day, Source- Purchased/water tanker (Bill enclosed)			
38	MCTC EXIM PVT. LTD.	B-239 OKHLA INDUSTRIAL AREA PHASE-I	01-08-2016	DPCC/EC/2/1/2016/15642	Automobile workshop cum service station including denting painting and washing. Automobile Servicing and Repair Station with Washing Activity with burner	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 01-08-2016 Authorisation Status Pending	Status of Pollution Control System (1)ETP installed. (a) Effluent analysis report dated 27-06-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes (2)ECS - N/A (a) Stack monitoring report for paint booth dated 29-06-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes (3)D.G.Set Noise Report : 1 (a) The unit has 1 D.G. Set(s) of 140 KVA. Noise monitoring report dated 06-07-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes (4) Inspection details: No (5) SCN u/s 31(A)/33(A)/5 of EPA details : No (6) Closure directions u/s 31(A)/33(A)/5 of EPA details : No Ground water- Nil Water Consumption- 14000 ltrs/day, Source- Outside (Copy of Proof / Water Purchase Bill not enclosed)	Effluent analysis report dated 27-06-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes Stack monitoring report of Paint Booth dated 29-06-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes The unit has 1 D.G. Set(s) of 140 KVA. Noise monitoring report dated 06-07-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	30-08-2016 Unit has applied for CTO on 01.08.2016 and also applied under HWM Authorization on 01.08.2016. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 As decided by the Committee, the unit was inspected by DPCC officials on 07.09.2016 and following were observed: - Unit found in operation. - Unit has installed ETP but same found not in operational condition. - Sludge drying bed not installed to collect the sludge. - No wet sludge was available at site some dry sludge stored in a PVC container. - Unit is not complying with the provisions of Hazardous Waste Mangement rules w.r.t. display board not updated, container not marked with specified label, date has not been indicated on each container and daily record of hazardous waste has not been maintained. - Adequate stack height with paint Booth not provided. - Flow meter at inlet & outlet of ETP not installed. - Logbook of ETP & record of hazardous waste not maintained. - As informed, source of water is through tanker bill could not be provided.	04-11-2016 Take action as per decision in file.

											As approved, Show Cause Notice u/s 33(A) of Water Act & u/s 31(A) of the Air Act & u/s 5 of Environment (Protection) Act, 1986 and Show Cause Notice for Refusal of Consent under Air Act & Water Act and Show Cause Notice for Refusal of Authorization under Hazardous & Other Wastes (Management and Transboundary Movement) Rules, 2016 issued to the unit on 30.09.2016. The unit has submitted reply on 18.10.2016 w.r.t. Show Cause Notice dated 30.09.2016 along with photographs of ETP, display board, photographs of hazardous waste, logbook of ETP and copy of tanker water bill. The unit has informed that ETP is running, proper display board has been maintained, record has been maintain in Form-3, hazardous waste stored in leak proof container under shed on pucca floor inside the premises and the unit has requested to withdraw the show cause notice. The unit has not submitted point wise reply w.r.t rectification of deficiencies observed during inspection and also not submitted full compliance for the same. Record for Hazardous Waste not provided by the Unit along with its reply dated 18.10.2016. File is under submission.	
39	NEHA SALES CORPORATION	L-4 AND 5, NEW MANDOLI INDUSTRIAL AREA	01-08-2016	DPCC/EC/2/1/2016/15646	MFG. OF COPPER INGOTS. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		ETP ---- N/A (2)ECS - Scrubber, Cyclone	Stack monitoring report dated 21-07-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes.	30-08-2016 Redevelopment Area Recommendation /	04-11-2016 Expedite inspection.

									(3)D.G.Set Noise Report : 1 (4) Water Consumption: 200 L/ Day Source: Outside Water (5) Ground Water: Nil	One number of parameters analyzed which are within prescribed limit. The unit has 1 D.G. Set(s) of 30 KVA. Noise monitoring report dated 18-07-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes number of parameters analyzed which are within prescribed limit.	Action Taken Details (EE/AEE) on 04-11-2016 Letter has been issued to the unit on 03.11.2016 for submitting the certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit and for installation of online monitoring system. Inspection yet to b conducted. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 Unit has submitted copy of electricity Bill (Energisation date 12.01.2006) and copy of Registration Certificate issued by Central Excise dated 3.07.1998 as a proof of its respective date of establishment prior to the notification of 07.02.2007.	
40	SHRI RAM ENTERPRISES	PLOT NO M-9,PHASE-I BADLI INDsutRIAL ESTATE	03-08-2016	DPCC/EC/2/1/2016/15658	MANUFACTURING OF ALUMINIUM CIRCLE. Aluminium Casting (except cupola furnace only), Rolling (with capacity less than 25 MT/day) and Annealing	Orange Renewal	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- N/A 2. ECS- Yes (wet scrubber) PNG fired casting pit furnace 3. D.G. set- No Plot Area- 425 sq.mt. Commissioning Date- 01.01.2011 Status of Ground Water Extraction-No 1. Water consumption- 20 L/day. a) Source of water- Outside (copy of water bill not submitted) Status of Inspection- No	Water(Effluent)-N/A Emission monitoring report - Report submitted issued by DPCC on 29.06.2016. Parameters are within prescribed limit. Noise Test Report- N/A	~~03-08-2016~~ Remarks/ATR on 03-11-2016 Letter issued on 29.09.2016 to the unit to install online monitoring system(OLMS) within 03 months. Recommendation / Action Taken Details (EE/AEE) on 27-09-2016 Letter issued on 26.09.2016 to install Online Monitoring System (OLMS) within three months.	04-11-2016 Reply awaited so case deferred.
41	JMP INDIA	P-13, KHASRA NO 48, MAHAVIR GALI, NEW MANDOLI INDUSTRIAL AREA, SHAHDARA	08-08-2016	DPCC/EC/2/1/2016/15696	MANUFACTURING OF COPPER INGOTS. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		(1) ETP ---- N/A (2) ECS - Wet Scrubber (3) D.G.Set: ...N/A... (4) Water Consumption: 130 L/ Day Source: Home (5) Ground Water: Nil	Stack monitoring report dated 14-06-2016 issued by SHRIRAM INSTITUTE submitted. Stack Test Report within Limit - Yes. One number of parameters analyzed which are within prescribed limit.	30-08-2016 Redevelopment Area Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Letter has been issued to the unit on	04-11-2016 Expedite inspection.

											03.11.2016 for submitting the certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit and for installation of online monitoring system. Inspection yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 Inspection yet to be conducted.	
42	A AND V ZIPPERS PVT. LTD.	E-46/3, OKHLA INDUSTRIAL AREA, PHASE-II	11-08-2016	DPCC/EC/2/1/2016/15780	BASE KITCHEN. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Operate	Non-SPI		Status of Pollution Control System (1)ETP - Yes (a) Effluent analysis report dated 01-07-2016 issued by SHRIRAM INSTITUTE submitted. Effluent Test Report within Limit - No. (2)ECS - N/A (3)D.G.Set- Yes (a) The unit has 2 D.G. Set(s) of 125 KVA. Noise monitoring report dated 27-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise monitoring report within Limit - Yes Status of Ground Water extraction : Nil Water consumption- 4800 litres/day , Source- DJB (Bill enclosed)	Effluent analysis report dated 01-07-2016 issued by SHRIRAM INSTITUTE submitted. Effluent Test Report within Limit - No . The unit has 2 D.G. Set(s) of 125 KVA. Noise monitoring report dated 27-05-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise monitoring report within Limit - Yes	30-08-2016 Unit has applied for CTE and CTO on 11.08.2016. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 As decided by the Committee, Show Cause Notice u/s 33(A) of Water Act issued on 22.09.2016. The unit has submitted replies on 29.09.2016 & 21.10.2016 w.r.t. Show Cause Notice dated 22.09.2016 along with Effluent Analysis Report from DPCC Laboratory. The unit has informed that they have installed ETP which is regularly operated and maintained by their operator with proper care. The unit has also informed that they would follow all the norms of DPCC and requested to withdraw the show cause notice. Effluent Analysis Report from DPCC Laboratory dated 10.10.2016, submitted by the Unit along with its Letter dated 21.10.2016, reveals that the parameters are within	04-11-2016 Show cause notice for refusal of consent, show cause notice u/s 31(A) of Air Act and u/s 33(A) of Water Act be issued for the deficiencies observed during inspection on 03.11.2016.

											the prescribed limit. As decided, inspection of the unit was carried out by the Officials / Representatives of DPCC on 03.11.2016 and following were observed- - Unit found in operation & engaged in the activity of Base Kitchen. - Unit has provided Oil & grease Trap at ground floor. - Unit has installed ETP (Operational) consists of Aeration tank, Equalization tank, Filters but capacity / size of the ETP is need to be increased & also requires to provide sludge drying bed. - Channelization system with hood are provided with 4 burners / range, however hood not provided with 2 burners / range & also stack height upto roof level.	
43	DURGA ALLOYS	E-2, NEW MANDOLI INDUSTRIAL AREA	11-08-2016	DPCC/EC/2/1/2016/15787	MFG. OF COPPER INGOTS Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Wet Scrubber (3)D.G.Set: ...N/A... (4) Water Consumption: 50 L/ Day Source: Outside Water (5) Ground Water: Nil	Stack monitoring report dated 27-06-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes. One number of parameters analyzed which are within prescribed limit.	30-08-2016 Redevelopment Area Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Letter has been issued to the unit on 02.11.2016 for submitting the certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit and for installation of online monitoring system. Inspection yet to be conducted. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016	04-11-2016 Expedite inspection.

											Inspection yet to be conducted.	
44	SHUBHAM METAL INDUSTRIES	223 KH NO.25 NEW MANDOLI INDUSTRIAL AREA DELHI-110093	12-08-2016	DPCC/EC/2/1/2016/15805	Manufacturing of Aluminium Circle and Sheets Aluminium Casting (except cupola furnace only), Rolling (with capacity less than 25 MT/day) and Annealing	Orange Operate	Non-SPI		(1)ETP ---- N/A (2)ECS - Scrubber, Cyclone (3)D.G.Set Noise Report : 1 (4) Water Consumption: 20 L/ Day Source: Other Source of Water (5) Ground Water: Nil	AR -Nil Stack monitoring report dated 25-05-2016 issued by DPCC submitted. The unit has 1 D.G. Set(s) of 125 KVA. Noise monitoring report dated 24-05-2016 issued by DPCC submitted.	12-07-2016 Redevelopment area. Application received online, no enclosure submitted. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 The unit has submitted a letter on 04.10.2016 with a copy of the Rent agreement dated 08.08.2005 and an undertaking from the Landlord indicating that the premises was rented to M/s Shubham Metals from 08.08.2005, as a proof for existence of the unit prior to date of MPD-2021 notification i.e. 7th February, 2007. As per the office order dated 20.05.2016, Undertaking from Landlord and copy Rent agreement is an acceptable document with regard to proof of Existence. However, the name of document is not listed in the minutes dated 02.08.2016. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 1. Online Monitoring system has been installed and provided User Name and Password to DPCC. 2.The unit has submitted Stack monitoring report dated 25-05-2016 issued by DPCC. As per the Stack Test Report, parameters are within Limit. 3. A joint inspection was conducted by the Officials of Industries Department, Govt. of Delhi, SDM and DPCC to identify the existence of the unit	04-11-2016 Consent to Operate granted for five years provided the fee is deposited within 15 days otherwise issue consent for one year.

											within the boundaries of redevelopment Area. The team visited the redevelopment area to identify the above said unit namely M/s Shubham Metal Industries, Plot No. 223, Kh. No. 25, New Mandoli Ind. Area, New Delhi-110093 whose location on the app Maps. ME found between the latitude and longitude of 28.711585 degree N and 77.309603 degree E. The outer land mark was found electricity pole no. 1997-1998. The member of Industry Department has confirmed that the unit is located within the boundaries of the redevelopment Area. 4. As per the document submitted as proof of existence of the unit prior to 07 Feb, 2007, the unit has submitted a electricity bill dated 28.04.2015 in the name of Smt. Pushpa Gupta w/o Sh. Suresh Kumar Mittal, 223, Main road, Kh. No.25 New Mandoli Ind. Area, Delhi-93, indicating energisation date is 02.01.2007. 5. Rent agreement submitted dated 21.05.2012 by the firm with Smt. Pushpa Gupta (Landlady) w/o Shri Suresh Kumar Mittal r/o D-248, Vivek Vihar, Delhi-95. 6. No proof of existence of the unit prior to the notification of MPD-2021 i.e 07.02.2007	
45	SHIV METAL WORKS	29, Q/6, STREET NO. 4K, ANAND PARBAT INDUSTRIAL AREA	16-08-2016	DPCC/EC/2/1/2016/15889	CASTING BY PIT FURNACE. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Renewal	Non-SPI	HWM Application No. 1 Application Date 06-07-2004 Authorisation Status Approved	Source of water:Outside (Copy of bill not provided) water consumption:40 litre/day Status of ground water:Nil Status of Pollution Control System	Stack Monitoring Report: (a) Stack monitoring report dated 01-08-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes	30-08-2016 It is a case of redevelopment area. Recommendation / Action Taken Details (EE/AEE) on 03-11-2016	04-11-2016 Reply awaited so case deferred.

								Authorisation Issue Date04-08-2004 Authorisation Expiry Date03-08-2006 HWM Application No.2 Application Date06-10-2006 Authorisation StatusPending	(1)ETP ---- N/A (2)ECS - stack attached to exhaust of pit furnace (3)D.G.Set: ...N/A Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details :No Closure directions u/s 31(A)/33(A)/5 of EPA details :No	-As decided, a letter regarding submitting the details about operation of the unit within 15 days failing which consent application be infructuous. Also send the letter at correspondence address was issued to the unit on 03.11.2016 Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 -As per decision an inspection of the unit has been carried out by DPCC, Officials on 22.09.2016. During inspection as informed by the neighbours unit has been closed from past three months. -A letter may be issued to submit details about operation of the unit within 15 days failing which consent application be infructuous.		
46	LAXMI PLASTIC	G-969, DSIDC NARELA INDUSTRIAL AREA	16-08-2016	DPCC/EC/2/1/2016/15903	MANUFACTURING OF PVC DANA WITH WASHING. Manufacturing of Reprocessed PVC Granules & Other Injection Moulded Items (using Scrap As Raw Material with Washing Activity)	Orange Operate	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- Yes 2. ECS- Yes (Stack connected to mixer) 3. D.G. set- No Plot Area- 350 sq.mt. Proposed Date-01.07.2004 Status of Ground Water Extraction-No 1. Water consumption- 4000 L/day. a) Source of water- DSIIIDC (copy of DSIIIDC water bill not submitted) Complaint against this unit made by Sh. Rohit Gupta. Status of Inspection- Yes(28.12.2015) Inspection findings- 1. Unit found operating and engaged in the activity of mfg. of plastic dana & plastic goods using plastic scrap as a raw material with trade effluent discharge. 2. No ECS installed. 3. No ETP installed and waste water is being discharged directly into sewer without any treatment. 4. Unit is operating	Water(Effluent)-report dated 28.07.2016 issued by FICCI submitted. Parameters are within prescribed limit. Stack monitoring report dated 26.05.2016 issued by Shriram Institute for Industrial Research submitted. Parameters are within prescribed limit. Noise Test Report- N/A	30-08-2016 - Remarks/ATR on 03-11-2016 SCN for refusal of consent issued on 24.10.2016. Letter to consent agencies seeking compliance of closure directions issued on 24.10.2016. Compliance is yet to be received. Recommendation / Action Taken Details (EE/AEE) on 27-09-2016 Inspection conducted on 19.09.2016 findings are as follows- 1. Unit found operating and engaged in the activity of mfg. of plastic dana & plastic goods using plastic scrap as a raw material with trade effluent discharge. 2. ETP found installed	04-11-2016 Reply awaited so case deferred.

[illegible]

											technical capabilities and equipment to handle plastic waste safely, may grant registration to the applicant on fulfilment of the conditions as may be laid down in terms of registration. sub-rule (8) says that Every State Pollution Control Board or Pollution Control Committee shall take a decision on the grant of registration within ninety days of receipt of an application which is complete in all respects. sub-rule (9) says that The registration granted under this rule shall initially be valid for a period of one year, unless revoked, suspended or cancelled and shall subsequently be granted for three years. Compliance of closure direction dated 28.04.2016 is not received from the concerned authorities.	
47	VYOME BIOSCIENCES PVT LTD	PLOT NO-465, GROUND FLOOR, PATPARGANJ INDUSTRIAL AREA	16-08-2016	DPCC/EC/2/1/2016/15908	LABORATORY/PHARMACEUTICAL RESEARCH DEVELOPMENT. Medicines / Pharmaceutical Formulation- without Boiler	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 16-08-2016 Authorisation Status Pending	(1)ETP ---- ETP (2)ECS - N/A (3)D.G.Set Noise Report : 1 (4) Water Consumption: 1000 L/ Day Source: Outside (5) Ground Water: Nil	Effluent analysis report dated 22-06-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes. 13 number of parameters analyzed which are within prescribed limit. The unit has 1 D.G. Set(s) of 100 KVA. Noise monitoring report dated 23-03-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes. number of parameters analyzed which are within prescribed limit.	30-08-2016 Recommended for Inspection Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 Inspection of the unit was conducted on 03.11.2016 and following were observed. 1. Unit found in operation and engaged in the activity of pharmaceuticals research development. 2. ETP was found installed at the backside of the premises. ETP consists of reaction cum settling tank, oil and grease tank and two chambers sludge drying beds, ACF and PSF. 3. ETP was not found	04-11-2016 Issue show cause notice for refusal of consent, show cause notice u/s 33(A) of Water Act and show cause notice u/s 5 of EP Act.

											in operation. Untreated effluent in the reaction cum settling tank was seen below the agitator (mixing). 4. No chemical was seen in the chemical dosing tanks. Lid of the side containers were found covered with significant deposition of fine dust which indicate that the unit rarely open the dosing tank for chemical storing. 5. SDBs found with improper filter media and the leachate pipes not connected to the collection tank. 6. No wet and dry sludge was seen. Recommendation / Action Taken Details (EE/AEE) on 20-09-2016 Inspection yet to be conducted.	
48	GKB RX LENS PVT. LTD.	E-26, B-1, EXTENSION, MOHAN CO-OPERATIVE INDUSTRIAL AREA	16-08-2016	DPCC/EC/2/1/2016/15933	MFG. OF OPHTHALMIC LENSES. Optical Glass (Surfacing/Grinding Only)	Orange Renewal	Non-SPI	HWM Application No. 1 Application Date 24-12-2008 Authorisation Status Pending	Status of Pollution Control System (1)ETP installed. (a) Effluent analysis report dated 18-05-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes (2)ECS - N/A (3)D.G.Set Noise Report : 1 (a) The unit has 1 D.G. Set(s) of 320 KVA. Noise monitoring report dated 16-05-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes Status of Ground Water extraction : Nil Water consumption:7960 ltrs/day , Source: outside (bill not enclosed).. In compliance of the order dated 11.08.2015 of Honble NGT in application no. 300 of 2013 in matter of Manoj Mishra and Ors versus Union of India and others.As per survey by DPCC, an inspection of the unit was carried out by Officials / Representatives of DPCC on 27.08.2015 and following were	(a) Effluent analysis report dated 18-05-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes (a) The unit has 1 D.G. Set(s) of 320 KVA. Noise monitoring report dated 16-05-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	30-08-2016 Unit has applied for Renewal of consent to operate on 16.08.2016. Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 As decided, unit was inspected by officials of DPCC on 07.10.2016 and following observation were made: 1. The unit was found in operation. 2. ETP found installed & operational. 3. Mechanism to convey effluent to ETP needs to be made proper. 4. Proper records of operation of ETP needs to be maintained. 5. pH of Treated water was checked as 10.5. 6. Backwash from ACF & DMF needs to be taken back to ETP. 7. Door of Acoustic enclosure found broken. 8. No records of	04-11-2016 Take action as per the decision in file.

									observed: (a) ETP found installed and in working condition. Effluent samples collected during inspection by DPCC lab. (b) No permission shown for extraction of ground water. (c) Log book maintained and shown for operation of ETP. Show Cause Notice u/s 33(A) of the Water Act & u/s 31(A) of the Air Act on 07.09.2015 and Letter to DC for groundwater extraction on 07.09.2015. Unit submitted its representation on 24.09.2015 w.r.t SCN along with photographs of ETP, copy of receipt for water test report & adequacy report of ETP and requested to grant 60 days time to submit renewal of CTO. Modified direction was issued to unit on 18.04.2016 to apply for application of renewal of CTO with all required documents. Unit has applied for Renewal of consent to operate(CTR) on 16.08.2016. In the CTR application the unit has informed that they are not extracting any ground water.	sludge found. Recommendation / Action Taken Details (EE/AEE) on 29-09-2016 Inspection is yet to be conducted.	
49	SETCO	69/2-A INDUSTRIAL AREA , NAJAFGHAR ROAD MOTI NAGAR BEHIND MOIT NAGAR BUS STAND	22-08-2016	DPCC/EC/2/1/2016/16000	SERVICING REPAIRING AND WASHING OF TWO WHEELERS 15 VEHICLES/DAY APP. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 22-08-2016 Authorisation Status Pending	Status of Pollution Control System (1)ETP ---- Other ETP Name : ETP (a) Effluent analysis report dated 01-08-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes (2)ECS - N/A (3)D.G.Set: ...N/A... Status of Ground Water extraction :Nil Status of Inspection :No	30-08-2016 Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 -As decided, a show cause notice for refusal of consent/authorization, show cause notice for closure u/s 31(A) of Air Act, u/s 33(A) of Water Act and u/s 5 of EPA was issued to the unit on 03.11.2016. Recommendation / Action Taken Details (EE/AEE) on 30-09-2016 As decided, an inspection was carried	04-11-2016 Reply awaited so case deferred.

									SCN u/s 31(A)/33(A)/5 of EPA details :No Closure directions u/s 31(A)/33(A)/5 of EPA details :No Water Consumption 1000 liters/ day and its source DJB (Cat-II). Bill enclosed.		out by DPCC officials on 27.09.2016 and following observations were made: -ETP installed but was not in operational condition. -By pass arrangements of effluent observed. -No hazardous waste guidelines found followed. -No hazardous found at site. -Used oil being sold out to local vendor. -Issue Show cause Notice for closure u/s 31(A) of Air Act, u/s 33(A) of Water Act and u/s 5 of EPA and Show cause Notice for refusal u/s 31(A) of Air Act, u/s 33(A) of Water Act and u/s 5 of EPA.	
50	SHRI MAHAVIR PULSES PVT. LTD.	F-1715, DSIDC, NARELA INDUSTRIAL AREA	07-09-2016	DPCC/EC/2/1/2016/16091	DAL MILL. Dal Mills	Orange Operate	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- N.A 2. ECS- Yes, Attached to Bag house 3. D.G. set- Yes 2x160 & 320 KVA Plot Area- 700 sq mt Date of commissioning - 15.06.2016 Status of Ground Water Extraction-No 1. Water consumption- 2000 L/day. a) Source of water- DSIIDC (copy of DSIIDC water bill submitted) Status of Inspection- No	Effluent analysis report - N.A Emission moniotring report - Issued from Shriram institute for industrial research on 08.08.2016. Parameters are within prescribed limit. Noise monitoring report issued from DPCC on 17.08.2016. Parameters are within prescribed limit.	27-09-2016 Recommendation / Action Taken Details (EE/AEE) on 03-11-2016 Previous decision to be implemented. File is under submission.	04-11-2016 Implement the earlier decision Dated 30.09.2016. Concerned In-charge, CMC may take necessary action.
51	ASHISH GARG	KHASRA NO 833/65, POLE NO 2033-2034, NEW MANDOLI INDUSTRIAL AREA	07-09-2016	DPCC/EC/2/1/2016/16098	MFG. OF COPPER INGOTS. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		Status of Pollution Control System (1)ETP ---- N/A (2)ECS - Scrubber, Cyclone (a) Stack monitoring report dated 22-08-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes . (3)D.G.Set Noise Report : (a) The unit has 2 D.G. Set(s) of 62.5 KVA(not in use) and 62.5 KVA. Noise monitoring report dated 19-08-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	Stack monitoring report dated 22-08-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes . D.G.Set Noise Report : (a) The unit has 2 D.G. Set(s) of 62.5 KVA(not in use) and 62.5 KVA. Noise monitoring report dated 19-08-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	04-11-2016 As per the decision taken on 30.09.2016 unit may be asked to submit certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit including other deficiencies in respect of the consent application.	04-11-2016 Ask the unit to submit certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit including other deficiencies in respect of the consent application.

									Status of Ground Water extraction : No. Water is purchased from outside, bill enclosed. The unit has submitted copy of Income Tax Return for the financial year 01.04.2004 to 31.03.2005 submitted to Income Tax Department on 01.04.2006 as proof of establishment before 07.02.2016. The unit has not installed online monitoring system.			
52	KRISH AUTOMOTORS PVT LTD	A-3 WAZIRPUR INDUSTRIAL AREA	19-09-2016	DPCC/EC/2/1/2016/16170	SERVICING / REPAIRING OF AUTOMOBILES. Automobile Servicing and Repair Station with Washing Activity with burner	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 19-09-2016 Authorisation Status Pending	Status of Pollution Control System (1)ETP installed (2)ECS - N/A. Status of Ground Water extraction : Nil Water consumption: 3.3 KLD and its source is corporation. The premises was inspected on 27.09.2016 with reference to complaint received through PGMS vide I.D. 201686083 and following were observed: - The unit has installed an ETP (batch type) but the same was not found in operation. However collection tank and reaction cum settling tank was filled with trade effluent and no dosing of coagulant was done in the reaction tank. - A bypass arrangement pipe was observed in a tank before collection tank and all the trade effluent generated from the washing section is being by passed without any treatment. - Logbook of ETP is being maintained since 1st of June 2016 and logbook of hazardous waste is being maintained since June 2016. - Quantity of ETP sludge and used oil stored are not matching with record i.e. less ETP sludge and more used oil was found stored. - The unit is not complying with the provisions of HWM rules as mentioned	(a) Effluent analysis report dated 23-06-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Effluent Test Report within Limit - Yes. (b) Emission monitoring report dated 18.06.2016 issued by FICCI RESEARCH ANALYSIS CENTRE for the existing Paint booth submitted and is within limit. stack height provided with the paint booth is 2m above roof level. (c) The unit has 1 D.G. Set(s) of 82.5 KVA. Noise monitoring report dated 18-06-2016 issued by FICCI RESEARCH ANALYSIS CENTRE submitted. Noise monitoring report within Limit - Yes.	29-09-2016 . Remarks / ATR on 03-11-2016 Unit has submitted its reply on 31.10.2016 in response to SCN issued on 18.10.2016 along with a copy of DJB bill and photograph of closure of overflow provision (bypass system). The unit has informed that the ETP (Batch Type) is operational and there is no bypass arrangement. It has been mentioned in the reply that there is overflow provisions in the tank which have now been closed permanently. The unit has informed that the logbook of ETP and Hazardous waste is being maintained and quantity of ETP sludge and used oil are matching with the record. However, no copy of ETP logbook and hazardous waste logbook have been enclosed with the reply. The unit may be inspected to verify the facts. Recommendation / Action Taken Details (EE/AEE) on 31-10-2016 As decided, SCN u/s 33(A) of Water, Act 31(A) of Air Act & u/s	04-11-2016 Inspection be conducted.

									in the point No. 23 above. - No permission of CGWA/DJB for borewell was shown.		5 of EP Act read along with HW rules and SCN for refusal of consent under Air Act & Water Act and Authorization under HW rules was issued on 18.10.2016. Reply is still awaited.	
53	KRISH DEVELOPERS PVT. LTD. (CITY PARK NORTH)	KH. NO.-51/19, VILLAGE BAKOLI	21-09-2016	DPCC/EC/2/1/2016/16186	HOTEL AND MOTELS WITH BANQUET AND PARTY LAWN. Hotel/ Guest Houses having 20 to 50 rooms (double bed) or 40 to 100 rooms (single bed) (excluding 3 Star and above) - not connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - not connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Renewal	Non-SPI		Status of Pollution Control system Devices- 1. STP-Yes 2. ECS- Yes (Kitchen emission channelization) 3. D.G. set- 4x 200KVA and 1x 250 KVA Plot Area-41,935.23 sq mt Date of Establishment - 01.09.2010 Status of Ground Water Extraction-Yes 1.Water consumption- 22000 L/day. Source- Outside (Packaged drinking water bill submitted) Status of Inspection- No MCD license submitted valid upto 31.03.2017. Police license submitted valid upto 31.03.2017. SCN issued on 24.08.2016 as unit has not applied for renewal of consent after expiry.	Effluent monitoring report issued on 23.08.2016 by DPCC. Parameters are within prescribed limit. Emission monitoring report- N/A Noise monitoring reports issued on 08.08.2016 by DPCC. Parameters are within prescribed limit.	03-11-2016 -	04-11-2016 Consent to Operate (Renewal) granted.
54	GIAN FOUNDRY WORKS	B-1 TO B-5, MAYAPURI INDUSTRIAL AREA, PHASE-II	21-09-2016	DPCC/EC/2/1/2016/16196	C.I. CASTING THROUGH PIT FURNACE. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		Source of Water: Outside (copy of bill not provided) Water Consumption:100 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP ---- N/A (2)ECS - Proposed (3)D.G.Set: ...N/A... -A complaint received in office and as approved,an inspection is conducted by DPCC officials on 10.02.2016 and unit found operating without taking consent and without ESC over cupola furnace. -A show cause notice was issued to the unit on 13.05.2016. -Unit failed to submit reply w.r.t show cause notice. -Accordingly, a closure direction was issued to the	Stack monitoring report: . (a) Stack monitoring report dated 07-09-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes	04-11-2016	04-11-2016 Inspection be conducted.

									unit on 19.07.2016. -Unit submit its reply w.r.t closure direction and submit its application for consent to establish and rectify the deficiencies observed during inspection and requested to revoke the closure direction. - As decided, a temporary revocation was issued to the unit on 22.08.2016 for 30 days for submitting consent to operate application with all requisite documents.			
55	S.A.S. COLOUR IMPACT	B-108, SECTOR-2, DSIIDC, BAWANA INDUSTRIAL AREA	21-09-2016	DPCC/EC/2/1/2016/16197	READYMADE JEANS WASHING. Readymade Garment (with Washing)	Orange Operate	Non-SPI		Status of Pollution Control system Devices- 1. ETP-Yes 2. ECS- Yes (Kitchen emission channelization) 3. D.G. set- No Plot Area-100 sq mt Date of Establishment - 01.09.2010 Status of Ground Water Extraction-No (As per consent form). Yes (as per previous inspection). 1.Water consumption- 4400 L/day. Source- DSIIDC (bill submitted) Status of Inspection- Yes (14.01.2016) 1. Unit found operating & engaged in the activity of Jeans washing. 2. No valid consent obtained from DPCC. 3. One borewell connection exists without permission from DJB/CGWA. 4. No ETP installed waste water is being discharged directly into sewer without any treatment. Show Cause Notice u/s 31 (A) of Air Act & 33(A) of Water Act issued on 24.02.2016 (in name of Yes a Yes Colour Impact Company). No Reply was submitted. Directions for closure issued on 29.04.2016(in name of Yes a Yes Colour Impact Company). Unit was again inspected on 01.09.2016 to check the operational status. During inspection, unit found operational & engaged in the activity of Jeans washing, No ETP installed & waste water is	Air (Emission)-N/A Water (Effluent)- Test Report (readymade garment washing) issued on 22.08.2016 by DPCC lab submitted. Parameters are within prescribed limit. Noise Test Report- N/A	03-11-2016 -	04-11-2016 Issue show cause notice for refusal of consent. Also seek compliance report from concerned agencies.

									being discharged directly without any treatment, HWM Rules are not complied with, No ECS installed over spray paint booth. Spray paint work not shown in consent applications. Compliance of closure directions yet to be received. Unit vide its letter on 27.09.2016 has requested for revocation of clousre directions.			
56	SHRI BALAJI MOTELS PVT. LTD.	KH. NO 92/16 MIN, 92/6, 92/15, 92/16 MIN, VILLAGE ALIPUR, JINDPUR ROAD	23-09-2016	DPCC/EC/2/1/2016/16207	MOTEL FOR 11 ROOMS. Hotel/ Guest Houses having less than 20 rooms (double bed) or 40 rooms (single bed) (excluding 3 Star and above) - not connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Renewal	Non-SPI		Status of Pollution Control system Devices- 1. ETP-Yes 2. ECS-Yes (Kitchen emission channelization) 3. D.G. set- 4x 125 KVA Plot Area-11897.75 sq mt Date of Commencement- May 2011 Status of Ground Water Extraction-No 1.Water consumption- 22000 L/day. Source- Outside (only packaged drinking bill submitted) Status of Inspection- No MCD license valid upto 31.03.2017.	Effluent monitoring report issued on 19.09.2016 by DPCC. Parameters are within prescribed limit. Emission monitoring report- N/A Noise monitoring report issued on 08.08.2016 by DPCC. Parameters are within prescribed limit.	03-11-2016 -	04-11-2016 Consent to Operate (Renewal) granted.
57	GALAXY AUTOMOBILES PVT LTD	28, DLF INDL. AREA, MOTI NAGAR	23-09-2016	DPCC/EC/2/1/2016/16208	CAR WASHING,DENTING AND PAINTING OF CARS. Automobile Servicing and Repair Station with Washing Activity with burner	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 23-09-2016 Authorisation Status Pending	Source of water: DJB, Category-II (Copy of bill enclosed) Water Consumption: 15000 litre/day Extraction of Ground Water: Nil D.G Set: 1 D.G Set of 365 KVA installed Status of Pollution Control System (1)ETP -working (2)ECS - working (3)D.G.Set Noise Report : 1 D.G. Set(s) of 365 KVA. Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details :No Closure directions u/s 31(A)/33(A)/5 of EPA details :No	Effluent analysis report: (a) Effluent analysis report dated 14-09-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes. Emission monitoring report: (a) Stack monitoring report of the stack attached to paint booth no. 1 (ground floor) dated 19-09-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes (b) Stack monitoring report of the stack attached to paint booth no. 2 (first floor) dated 19-09-2016 issued by DPCC submitted. Stack Test Report within Limit - Yes (c) Stack monitoring report of the stack attached to paint booth no. 3 (second floor) dated 19-09-2016 issued by DPCC submitted. Stack Test Report within Limit -	04-11-2016 As decided in the meeting dated 27.06.2016 Consent to Establish granted with the condition that unit shall submit the proof that the water is being obtained from the authorised source at the time of applying for Consent to Operate.Accordingly, unit has applied for consent to operate on 23.09.2016 also submitted a copy of DJB connection of Category-II. Hence, CTO may be granted.	04-11-2016 Consent to Operate and Authorization under HWM Rules granted.

										Yes Noise Monitoring report: (a) The unit has 1 D.G. Set(s) of 365 KVA. Noise monitoring report dated 16-09-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes An inspection was conducted by DPCC officials on 04.11.2016 and following observations were made: -During inspection unit found operational. -ETP installed and was also operational. -HWM Guidelines found followed. -Used oil being sold out to the registered recycler. -Log book found maintained. -DG Set has proper acoustic and adequate stack.		
58	SARTAJ HOTELS APARTMENT & VILLAS PVT LTD	CELEBRATION GARDEN NH 8 ADJOINING SHIV MURTI RANGPURI	23-09-2016	DPCC/EC/2/1/2016/16212	MOTEL WITH 20 ROOMS. Hotel/ Guest Houses having 20 to 50 rooms (double bed) or 40 to 100 rooms (single bed) (excluding 3 Star and above) - not connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Operate	Non-SPI		Source of water: outside (Copy of bill not enclosed) Water Consumption: 20000 litre/day Extraction of Ground Water: Nil D.G Set: N/A Status of Pollution Control System (1)ETP -working (2)ECS - N/A Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details :No Closure directions u/s 31(A)/33(A)/5 of EPA details :No	Effluent analysis report: (a) Effluent analysis report dated 04-08-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes	03-11-2016	04-11-2016 Consent to Establish and Consent to Operate granted.
59	GURDIAL SINGH & SONS	A-10, PH-I BADLI INDL. AREA	27-09-2016	DPCC/EC/2/1/2016/16235	MFG. OF L.P.G.REGULATOR. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		Status of Pollution Control system/Devices- 1. ETP-N/A 2. ECS- Yes Stack attached to melting furnace and Stack with dust collector and paint booth 3. D.G. set- Yes, 62.5 KVA Plot Area- 250 sq mt Proposed Date- 01.10.2011 Status of Ground Water Extraction-Yes 1. Water consumption- 800 L/day. a) Source of water- DJB (copy of water bill submitted)	Air (Emission)-Stack Report (Paint booth) and - Stack Report (Melting furnance) dated 21.09.2016 issued by DPCC lab submitted. Parameters are within prescribed limit. Water (Effluent)- N/A Noise Test Report- Report issued on 15.09.2016 by DPCC lab submitted. Parameters are within prescribed limit.	04-11-2016	04-11-2016 Consent to Operate granted. Also correct the address of the unit i.e. A-10, Phase-III, Badli Industrial Estate. Concerned Incharge, CMC to take necessary action in this regard.

									Status of Inspection- No			
									Actual address of the unit is A-10, Phase-III (as mentioned in undertaking, consent form, C.A. certificate, CETP receipt and previous CTE application receipt no. 37991 dated 01.09.2011)			
60	SHAKTI INSULATORS	56-A, NAJAFGARH ROAD INDUSTRIAL AREA	28-09-2016	DPCC/EC/2/1/2016/16241	Copper Wire Drawing with enamelling. Copper Wire Drawing with Super Enamelling (Dry Process)	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 28-09-2016 Authorisation Status Pending	Source of water: DJB, Category-II (Copy of bill enclosed) Water Consumption: 100 litre/day Extraction of Ground Water: Nil D.G Set: N/A Status of Pollution Control System (1)ETP ---- N/A (2)ECS - Stack attached to furnace Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details :No Closure directions u/s 31(A)/33(A)/5 of EPA details :No	Stack monitoring report: (a)Stack monitoring report of the stack attached to furnace dated - 02.04.2016 - issued by - FICCI Research and Analysis Center submitted and parameters found within limit.	03-11-2016 As decided in the meeting dated 27.06.2016 consent to establish was granted with the condition that the unit shall apply for Consent to Operate within 03 months.Accordingly, unit has applied for consent to operate on 28.09.2016. Hence, CTO may be granted.	04-11-2016 Inspection be conducted.
61	SHAN ENTERPRISES	B-2618, II FLOOR, DSIIDC, NARELA INDUSTRIAL AREA	28-09-2016	DPCC/EC/2/1/2016/16244	Job work of washing of readymade Garments (With oil Fired Boiler) Readymade Garment (with Washing) with Boiler	Orange Operate	Non-SPI		Directions for closure issued on 09.09.2016. Compliance from concerned departments is yet to be received. Unit has requested for revocation vide its letter dated 29.09.2016 stated that only washing of readymade garment is done, coal fired boiler is converted in oil fired, etc.	Air (Emission)-Yes, (Diesel fired Boiler stack) Test report dated 26.09.2016 issued by DPCC lab meeting the norms. Water (Effluent)- Report issued on 26.09.2016 by DPCC lab submitted. Parameters are within prescribed limit. Noise Test Report- N/A	03-11-2016 -	04-11-2016 Inspection be conducted.
62	CREATIVE CLUB	H-1402, DSIIDC, NARELA INDUSTRIAL AREA	28-09-2016	DPCC/EC/2/1/2016/16245	Job work of Washing of Readymade Garments (Without Boiler). Readymade Garment (with Washing)	Orange Operate	Non-SPI		Status of Pollution Control system/Devices- 1. ETP- Yes 2. ECS- No 3. D.G. set- N/A Plot Area- 350 sq mt Date of Commissioning- 22.10. 2016 Status of Ground Water Extraction-No 1. Water consumption- 10000 L/day. a) Source of water- Outside(copy of outside water bill not submitted) Status of Inspection- 11.01.2016 1. Unit found operating & engaged in the activity of Dyeing & washing of jeans w/o consent from DPCC. 2. No ETP installed waste water is being dicahrged	Air (Emission)- N/A Water (Effluent)- Report issued on 26.09.2016 by DPCC lab submitted. Parameters are within prescribed limit. Noise Test Report- N/A	04-11-2016 -	04-11-2016 Inspection be conducted. IT Cell to correct the data of effluent discharge.

									directly into sewer w/o any treatment and not connected with conveyance system of CETP. 3. No ECS over paint booths provided. 4. HWM rules not complied with. 5. Borewell connection exists w/o permission from DJB/CGWA. Show Cause Notice u/s 31 (A) of Air Act, 33(A) of Water Act & u/s 5 of EPA issued on 24.02.2016. Modified directions u/s 31 (A) of Air act, u/s 33 (A) of Water act and u/s 5 of EPA to comply with the pollution control norms & to apply for consent & authorisation issued on 29.04.2016 Directions for closure issued on 09.09.2016. Compliance from concerned departments is yet to be received. Dyeing activity and Spray paint work observed during previous inspection but same is not shown in consent application. In consent application form unit mentioned effluent discharge 8000 L/day but In DPCC consent application software IT cell inter 600 L/day.			
63	VINAYAK COPPER PRIVATE LIMITED	KHASRA NO 12/21/2, E-3A, NEW MANDOLI INDUSTRIAL AREA	28-09-2016	DPCC/EC/2/1/2016/16252	MFG. OF COPPER INGOTS. Casting of Ferrous/ Non Ferrous Metal (except cupola furnace Only)	Orange Operate	Non-SPI		Status of Pollution Control System (1)ETP - N/A (2)ECS - Scrubber, Cyclone (3)D.G.Set Noise Report : 1 (a) The unit has 1 D.G. Set(s) of 62.5 KVA. Noise monitoring report dated 18-07-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes number of parameters analyzed which are within limit / beyond prescribed limit. (b) Stack monitoring report.	N/A.	17-10-2016 Recommended for inspection and as per the decision taken in the meeting of CMC of II(b) category held on 06.09.2016, ask the unit to submit certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit including other deficiencies in respect of the consent application, if any, submitted by the unit. Also inspection be conducted.	04-11-2016 Ask the unit to submit certificate, in original, from Industries Department, Govt. of Delhi regarding location of the unit is within the boundary of the notified Redevelopment Area clearly mentioning the name & address of the unit including other deficiencies in respect of the consent application, if any, submitted by the unit. Also inspection be conducted.
64	SHREE GANESH POLYMERS	PLOT NO 126, KH. NO 45/17, SWARN PARK, MUNDKA	06-10-2016	DPCC/EC/2/1/2016/16269	Bakelite Powder mfg. using Phenol Formaldehyde Resin As Raw Material and Bakelite Products	Orange Operate	Non-SPI		Source of water:outside water consumption:20 litres/day Status of ground water:Nil	Emission monitoring report: (b) Stack monitoring report dated 30-09-2016	03-11-2016 consent to operate may be granted.	04-11-2016 Consent to Operate granted for five years provided the fee is

		INDUSTRIAL AREA			Bakelite Powder mfg. using Phenol Formaldehyde Resin As Raw Material and Bakelite Products				Status of Pollution Control System (1)ETP ---- N/A (2)ECS - Bag Filter / Bag House (3)D.G.Set: 1 D.G of 62.5 KVA Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details :No Closure directions u/s 31(A)/33(A)/5 of EPA details :No -A letter from the office of Sub- Divisional Magistrate (Punjabi Bagh) received in our office 22.07.2011 in which it is mentioned that Khasra No. 45/17 situated at the Plot No. 126 colony known as Swarn Park Industrial Area, North Railway Line in the area of Village Mundka, Delhi-110041 falls within the boundary of layout plan of DSIIDC for proposed re-development as Industrial Area. -Unit has submitted a certificate of registration on under D-VAT dated 18.12.2006 as a proof of establishment of the unit prior to 07-02-2007.	issued by DPCC submitted. Stack Test Report within Limit - Yes Noise Monitoring report: (a) The unit has 1 D.G. Set(s) of 62.5 KVA. Noise monitoring report dated 08-09-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes		deposited within 15 days otherwise issue consent for one year.
65	SHIV KUMAR (UNIT-I)	N1-112, SECTOR-5, DSIIDC, BAWANA INDUSTRIAL AREA	12-10-2016		Job work of Washing of Readymade Garments (With oil Fired Boiler) Readymade Garment (with Washing) with Boiler	Orange Operate	Non-SPI		Directions for Closure issued on 23.09.2016. Reply received on 14.10.2016 & 21.10.2016 wherein the unit has applied for CTO on 13.10.2016 and also submitted the Security Bond of Rs. 5 lakhs along with undertaking submitted. Hard copy of application for consent to operate not submitted. Common File is under submission with proposal for revocation of closure directions temporarily for 45 days for necessary testing/compliance & to apply for Consent to operate/authorisation.	-	03-11-2016	04-11-2016 Take action as per decision in file. Ask the unit to submit hard copy of consent application. Also inspection be conducted.
66	DIVINE AUTOTECH PVT. LTD.	26, RAJASTHANI UDYOG NAGAR INDUSTRIAL	13-10-2016	DPCC/EC/2/1/2016/16280	AUTOMOBILE SERVICING, REPAIRING, DENTING AND PAINTING WITH WASHING. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application 08-10-	Status of Pollution Control system Devices- 1. ETP-Yes 2. ECS-N/A 3. D.G. set- 1x 62.5 KVA Plot Area-1505 sq mt	Effluent monitoring report issued on 30.08.2016 by DPCC. Parameters are within prescribed llimt. Emission monitoring	04-11-2016	04-11-2016 Inspection conducted on 13.10.2016 and deficiencies observed. Issue show cause notice for refusal of

		AREA, G.T. KARNAL ROAD			Denting and Painting of Vehicles			Date Authorisation Status	2016 Pending	Date of Commencement- 01.08.2016 Status of Ground Water Extraction-No 1.Water consumption- 2500 L/day. Source- DJB (bill submitted) Status of Inspection- Yes(13.10.2015) and inspection findings are as follows: 1. ETP of the unit is not found in operation. Connection of the pump with the air blower found disconnected. 2. No wet/dry sludge was seen in sludge drying beds. 3. HWM measures have not been taken. 4. No proper log book of ETP was observed. Applied Form-I under HWM rules on 13.10.2016.	report- N/A Noise monitoring report issued on 29.08.2016 by DPCC. Parameters are within prescribed limit.		consent/authorization, show cause notice u/s 33(A) of Water Act and u/s 5 of EP Act.
67	J.G. WORKS	B-119, OKHLA INDUSTRIAL AREA-I	13-10-2016	DPCC/EC/2/1/2016/16291	Packing and Dispensing of Chemicals Laboratory Reagents and Kits	Orange Renewal	Non-SPI	HWM Application No. Application Date Authorisation Status Authorisation Issue Date Authorisation Expiry Date HWM Application No. Application Date Authorisation Status	1 20-01- 2004 Approved 22-09- 2004 21-09- 2006 2 10-10- 2016 Pending	Status of Pollution Control System (1)ETP - ETP - Physiochemical (a) Effluent analysis report dated 22-09-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes. (2)ECS - N/A (3)D.G.Set: ...N/A... Water consumption - 200 ltrs /day Status of Ground Water extraction : Nil Source of water - Outside Status of Inspection : NA SCN u/s 33(A) and the water Act & u/s 31(A) of the Air act issued on 28.06.2016 as unit has not applied for renewal of consent to operate after expiry period of previous consent application dated 13.02.2008 and Effluent Analysis Report of effluent sample collected by DPCC Lab on 10.03.2016 not meeting the prescribed standards. The unit has submitted reply on 15.07.2016 w.r.t. Show Cause Notice	Effluent analysis report dated 22-09-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes	04-11-2016	04-11-2016 Inspection be conducted.

									informing that they have improved the operational efficiency of existing ETP & the issue of high lead should not occur, regarding renewal the matter had got delayed due to their activity not being in the list earlier & this has been resolved and taking appropriate action to re-file application. The unit has also informed that for Consent, their samples have to be retested along with other formalities & approaching approved laboratory for this and requested for grant of 60 days time to file application. The unit has submitted letter 13.07.2016 informing that they had applied for Consent to operate and Authorization under Hazardous Waste Management Rules on 13.10.2016			
68	CHANSON HOSPITALITY PVT. LTD	30/23/2/2 MIN ON MAIN ROHTAK ROAD, NANGLOI JAT	14-10-2016	DPCC/EC/2/1/2016/16297	BANQUET HALL. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Operate	Non-SPI		source of water: outside (copy of bill enclosed) water consumption detail: 15000 liter per day ground water extraction status: nil DG set : nil Status of Pollution Control System (1)ETP - working (2)ECS - N/A - As decided in the meeting file be put up administratively and the brief of the unit mentioned below: - A complaint received against the unit on 06.07.2015. accordingly it has been decided to inspect the unit. - An inspection was carried out on 11.12.2015 and following observations were made: -CTE obtained not applied for CTO yet. -ETP installed but found in defunct condition. -Waste water directly being discharged in to sewer. -No channelization done in the kitchen. -In kitchen area lot of bad	Effluent analysis report (a) Effluent analysis report dated 23-08-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes	03-11-2016 Consent to establish and consent to operate may be granted. Also, closure direction be revoked.	04-11-2016 Consent to Operate granted. Also revoke the directions for closure issued on 24.05.2016.

									smell observed. - D.G Set have acoustic enclosure but inadequate stack height. - One borewell observed no permission shown. -No MCD & Delhi Police License shown for operation of banquet hall. -Only banqueting is done. No restaurant exists. -A Show Cause Notice u/s 31 (A) & 33 (A) issued to the unit on 25.01.2016. - Unit failed to submit any reply w.r.t above mentioned SCN. -As decided, closure direction was issued to the unit on 24.05.2016.			
69	CHANSON BANQUET	17A, SHIVAJI MARG, NAJAFGARH ROAD INDUSTRIAL AREA	14-10-2016	DPCC/EC/2/1/2016/16298	BANQUET HALL. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Operate	Non-SPI		source of water: outside (copy of bill not enclosed) water consumption detail: 15000 liter per day ground water extraction status: nil DG set : nil Status of Pollution Control System (1)ETP - working (2)ECS - N/A -As decided in the meeting file put up administratively and the brief about the unit is mentioned below. -As per the order of Honourable NGT in the matter of Manoj Mishra V/s Union of India and Ors in O.A No. 06 of 2012 and O.A No. 300 of 2013 has ordered on 11.08.2015 that the industries which are operating in any of the 28 industrial clustered without consent of DPCC should be served with notice of closure. - As inspection of the unit was carried out on 28.05.2015 and various deficiencies were observed. -A Show Cause Notice u/s 31 (A) & 33(a) was issued to the unit on 08.09.2015 and also a letter to concerned Dy. commissioner w.r.t extraction of ground water on 08.09.2015. -An inspection was carried	Effluent analysis report (a) Effluent analysis report dated 20-09-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes	03-11-2016 Consent to establish and consent to operate may be granted. Also, Closure direction may be revoked.	04-11-2016 Consent to Operate granted. Also revoke the directions for closure issued on 26.05.2016.

									out on 03.02.2016 and following observations were made: -Unit operating since January, 2015. -Not applied for CTE & CTO yet. - No channelization done in the kitchen. -ETP installed but was totally defunct. only structure found laying at roof of the building. -Hundred percent waste water is being discharged in to sewer without treatment. - D.G Set has inadequate stack height. -Unit has one borewell without permission. -A reminder issued to Dy. commissioner w.r.t extraction of ground water on 15.12.2015. -A closure direction u/s 31(A) & 33(A) was issued to the unit on 26.05.2016. -CTE may be granted and also, closure direction be revoked temporarily for 45 days to apply CTO application.			
70	R.R. AUTOMOBILES	71/1, GROUND FLOOR AND BASEMENT, SHIVAJI MARG, NAJAFGARH ROAD INDUSTRIAL AREA	18-10-2016	DPCC/EC/2/1/2016/16304	AUTOMOBILE REPAIR AND SERVICING WITH WASHING. Automobile Servicing and Repair Station with Washing Activity	Orange Operate	Non-SPI	HWM Application No. 1 Application Date 17-10-2016 Authorisation Status Pending	Status of Pollution Control System Water Consumption: 2500 Litres/ Day Source of Water: Outside (copy of bill not provided) Status of Ground Water extraction : Nil (1)ETP ---- ETP - Physiochemical (2)ECS - N/A (3)D.G.Set Noise Report : 1 D.G. Set(s) of 50 KVA Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No An inspection was conducted by DPCC officials on 04.11.2016 and following observations were made: -During inspection unit found operational. -ETP intalled and was also operational.	(a) Effluent analysis report dated 26-08-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes (b) The unit has 1 D.G. Set(s) of 50 KVA. Noise monitoring report dated 24-08-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	04-11-2016 As deiced in the meeting dated 27.06.2016 Consent to Establish granted with the condition that the unit shall apply for Consent to Operate within 03 months. Accordingly, unit has applied for consent to operate on 18.10.2016. Hence, consent to operate may be granted.	04-11-2016 Consent to Operate and Authorization under HWM Rules granted.

									-HWM Guidelines found followed. -Used oil being sold out to the registered recycler i.e. M/s Bharat Oil Company. -Log book found maintained. -DG Set has proper acoustic and adequate stack provided.			
71	HOTEL SWATI (A UNIT OF SHUDH HOSPITALITY PRIVATE LIMITED)	PLOT NO 15-A/56, W.E.A, KAROL BAGH	20-10-2016	DPCC/EC/2/1/2016/16312	GUEST HOUSE (34 ROOMS). Hotel/ Guest Houses having 20 to 50 rooms (double bed) or 40 to 100 rooms (single bed) (excluding 3 Star and above) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and not having Kitchen and / or Laundry with Boiler	Orange Operate	Non-SPI		Status of Pollution Control system Devices- 1. ETP- Yes (Oil & Grease Trap) 2. ECS- Yes (Stack attached to Oil fired boiler) 3. D.G. set- 1x 160 KVA Plot Area- 224 sq mt Date of Commencement- 01.01.2008 Status of Ground Water Extraction-No 1.Water consumption- 1300 L/day. Source- DJB (bill submitted) Status of Inspection- No Unit has submitted Copy of MCD license valid upto 31.03.2017	Emission Monitoring Report issued on 21.09.2016 by DPCC lab submitted. Parameters are within prescribed limit. Effluent Analysis Report- N/A Noise Monitoring Report issued on 20.09.2016 by DPCC lab submitted. Parameters are within prescribed limit.	04-11-2016 -	04-11-2016 Consent to Operate granted.
72	HOTEL SWATI DELUX (A UNIT OF SHUDH HOSPITALITY PRIVATE LIMITED)	PLOT NO 17-A/32, WEA, GURUDWARA ROAD, KAROL BAGH	20-10-2016	DPCC/EC/2/1/2016/16313	GUEST HOUSE (44 ROOMS). Hotel/ Guest Houses having 20 to 50 rooms (double bed) or 40 to 100 rooms (single bed) (excluding 3 Star and above) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and not having Kitchen and / or Laundry with Boiler	Orange Operate	Non-SPI		Status of Pollution Control system Devices- 1. ETP- Yes (Oil & Grease Trap) 2. ECS-Yes (Stack attached to Oil fired boiler) 3. D.G. set- 1x 180 KVA Plot Area-298 sq mt Date of Commencement- 01.01.2008 Status of Ground Water Extraction- No 1.Water consumption- 1500 L/day Source- DJB (bill submitted) Status of Inspection- No Unit has submitted Copy of MCD license valid upto 31.03.2017	Emission Monitoring Report issued on 21.09.2016 by DPCC lab submitted. Parameters are within prescribed limit. Effluent Analysis Report- N/A Noise Monitoring Report issued on 20.09.2016 by DPCC lab submitted. Parameters are within prescribed limit.	04-11-2016 -	04-11-2016 Consent to Operate granted.
73	RAJ VATIKA (A UNIT OF KHURANA HOSPITALITIES)	876, EAST PARK ROAD, KAROL BAGH	20-10-2016	DPCC/EC/2/1/2016/16314	BANQUET HALL. Restaurants/Eating Houses / Dhabas and other such establishments (with minimum seating capacity of 101) / Banquet Halls/ Party Lawns (with minimum Floor area 100 m2) and /Sweet Shops/ Halwais and Other such Establishments (with Annual Average Production of one Tonne/Day or more) - connected to / Discharging Effluent into Public / Municipal / DJB Sewer and having Kitchen and / or Laundry without Boiler	Orange Operate	Non-SPI		1. ETP-Yes 2. ECS-Yes(Kitchen emission channelisation) 3. D.G. set- 2x 125 KVA Plot Area-1291 sq mt Date of Commencement- 01.09.2014 Status of Ground Water Extraction-No 1.Water consumption- 3000 L/day. Source- DJB (Bill submitted) Status of Inspection- No Unit has submitted Copy of MCD license valid upto 31.03.2017 Unit has not submitted photographs of and	Effluent Analysis Report issued on 09.09.2016 by DPCC lab submitted. Parameters are within prescribed limit. Emission Monitoring Report- Not submitted Noise Monitoring Report issued on 12.07.2016 by DPCC lab submitted. Parameters are within prescribed limit.	04-11-2016 -	04-11-2016 Consent to Operate granted however to be issued after submission of photographs and details(size/dimensions) of ETP as per latest RESDH policy.

74	INDERPRASTHA HOLIDAY RESORTS PVT. LTD.	42/44 MIN. (1-14), 44/4(4-16), 44/5(2-8), 44/6(4-16), 44/7(4-16), 44/14/1 MIN. (0-8) , 44/15/1 MIN. (1-12)OF VILLAGE TIKRI KALAN NEW DELHI- 110041	28-10-2016	DPCC/EC/2/1/2016/16352	Motel and Banquesting Hotel/ Guest Houses having less than 20 rooms (double bed) or 40 rooms (single bed) (excluding 3 Star and above) - not connected to / Discharging Effluent into Public / Municipal / DJB Sewer and not having Kitchen and / or Laundry without Boiler	Orange Operate	Non-SPI		details(size/dimensions of Water Consumption-12000 Litres/ Day Source of Water- MCD (copy of bill not provided) Status of Ground Water extraction :Nil Status of Pollution Control System (1)ETP ---- Other ETP Name : STP (2)ECS - N/A (3)D.G.Set Noise Report : 2 D.G. Set(s) of 62.5 KVA(not in use) and 125 KVA Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	Noise- The unit has 2 D.G. Set(s) of 62.5 KVA(not in use) and 125 KVA. Noise monitoring report dated 30-05-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	11-07-2016 Hard copy of application is not provided. Recommendation / Action Taken Details (EE/AEE) on 03-11- 2016 -Unit submit its hard copies of consent to operate application along with required documents on 28.10.2016. -As decided an inspection was conducted by DPCC officials on 31.10.2016 and following observation were made: -During inspection the said motel/ Banquet hall found operational. -Unit has applied for CTO on 28.10.2016. -STP installed and was found operational. -DG Sets have proper acoustic and adequate stack height. -Unit has obtained CTE. -Unit is using DJB water and ground water. -One borewell exists. Consent to operate may be granted. Recommendation / Action Taken Details (EE/AEE) on 21-09- 2016 -A letter yet to be issued regarding of submission of hard copies of consent application along with required documents.	04-11-2016 Consent to Operate granted.
----	---	---	------------	------------------------	--	-------------------	---------	--	---	--	--	--



CONSENT MANAGEMENT

Decisions taken by the Committee for II(b) Category cases headed by Member Secretary DPCC in its 15th meeting on 04.11.2016 w.r.t. Table Agenda Item No 1- 03 Pending Cases of Consent to Operate of CMC-IV (Annexure III).

S. No.	Industry Name	Address	Date of Application	Application No	Activities / Product	Consent Application [CTE / CTO / CTO(R)]	Category (SPI/Non SPI)	Authorization Status (Granted/Applied - Fresh/Renewal)	Brief of Case	Status of Test Report(s)	Remarks (Whether unit fulfills all conditions for grant of Consent / Authorisation)	Decison
1	NORTH WEST SALES AND MARKETING LIMITED	A-40, COMMUNITY CENTRE, PASCHIM PURI	22-09-2015	DPCC/EC/2/1/2015/11861	SHOPPING COMPLEX. Shopping Malls, Housing / Commercial/ Office Complexes	Orange Operate	Non-SPI		Water Consumption : 45 KLD / day Source of Water:Corporation & Outside copy of bill for DJB Connection (CAT-II) provided but copy of outside purchase water bill not provided. Status of Pollution Control System (1)STP- Working (2)ECS - N/A (3)D.G. Set : 2 x 650 KVA (4) Inspection details: No (5) SCN u/s 31(A)/33(A)/5 of EPA details : No (6) Closure directions u/s 31(A)/33(A)/5 of EPA details : No (8) Plot Area : 2910 sqm and Built up area : 8470.99 sqm. (9) Date of Commissioning of Construction : 25.01.2012 (10) Date of completion / proposed date of completion of construction : December, 2014 (11) Date of Year of Commencement of Production : December, 2014.	Effluent: (a) AR dated October,2015 issued by Jamia Milia Islamia submitted. (b) Effluent analysis report dated 18-09-2015 issued by DPCC submitted. Effluent Test Report within Limit - Yes Noise: (a) The unit has 2 D.G. Set(s) of 625 KVA and 625 KVA. Noise monitoring report dated 27-03-2015 issued by DPCC submitted. Noise monitoring report within Limit - Yes (b) The unit has 2 D.G. Set(s) of 625 KVA and 625 KVA. Noise monitoring report dated 27-03-2015 issued by DPCC submitted. Noise monitoring report within Limit - Yes	17-08-2016 copy of outside purchase water bill not provided. Remarks/ ATR on 03-10-2016 .	04-11-2016 Consent to Operate granted.
2	SANGAM THEATRE PVT. LTD.	PLOT NO 9, SECTOR-9, R.K. PURAM	10-03-2016	DPCC/EC/2/1/2016/13936	PVR and Commercial Complex. Shopping Malls, Housing / Commercial/ Office Complexes	Orange Operate	Non-SPI		Source of Water: Delhi Jal Board (CAT-II) copy of bill provided Water Consumption: 50000 Litres/ Day Status of Ground Water extraction : Nil Status of Pollution Control System (1)ETP ---- ETP - Bio-logical (2)ECS - N/A	Water Effluent: (a)AR dated March, 2016 issued by Jamia Milia Islamia submitted. (b)Effluent analysis report dated 05-02-2016 issued by DPCC submitted. Effluent Test Report within Limit - Yes Noise Emission: (a) The unit has 2 D.G. Set(s) of 625KVA and 625 KVA. Noise monitoring report dated 07-01-2016 issued by DPCC	04-10-2016 . Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 -As decided, an inspection was conducted by DPCC officials on 2-11-16 and following observations were made:	04-11-2016 Consent to Operate granted.

									(3)D.G.Set Noise Report : 2 D.G. Set(s) of 625KVA and 625 KVA Status of Inspection : No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	submitted. Noise monitoring report within Limit - Yes (b)The unit has 2 D.G. Set(s) of 625KVA and 625 KVA. Noise monitoring report dated 07-01-2016 issued by DPCC submitted. Noise monitoring report within Limit - Yes	-During inspection unit found operational and engaged in the activity of cinema theater and restaurants. -ETP installed in the basement of the premises found functional -Log book of the ETP maintained. -Unit is having two DG Sets of capacity 600 KVA installed in acoustic enclosure with adequate stack height. -Flow meter installed at inlet and outlet.	
3	MURTI HOSPITALITY PVT. LTD. (CITY PARK WEST)	85/15/2,86/12/2,86/19,86/20,86/1,86/10,86/11/1,86/12/1 & 78/21, VILLAGE GHEWRA, HIRANKUNDNA MORE	14-03-2016	DPCC/EC/2/1/2016/13967	Hotels/ Motels for 16 rooms. Hotels with less than 20 bed rooms having kitchen and/or laundry and connected to public/municipal/DJB sewer	Orange Operate	Non-SPI		Status of Pollution Control System (1)ETP ---- ETP - Physiochemical (a) AR dated 25.04.2014 issued by DTU submitted. (b) Effluent analysis report dated 11.12.2015 issued by DPCC submitted. (2)ECS - N/A (3)D.G.Set Noise Report : 3 (a) The unit has 3 D.G. Set(s) of 250,250 and 250 KVA. Noise monitoring report dated 06-11-2015 issued by MAULANA AZAD MEDICAL COLLEGE submitted. Noise monitoring report within Limit - Yes Status of Ground Water extraction : Nil Source of Water: 45 KLD from DJB and tanker (as per undertaking)(copy of DJB bill enclosed) Status of Inspection :No SCN u/s 31(A)/33(A)/5 of EPA details : No Closure directions u/s 31(A)/33(A)/5 of EPA details : No	1. Effluent analysis report dated 11.12.2015 issued by DPCC submitted. Report within Limit - Yes 2. Noise monitoring report dated 06-11-2015 issued by MAULANA AZAD MEDICAL COLLEGE submitted. Noise monitoring report within Limit - Yes	11-07-2016 . Recommendation / Action Taken Details (EE/AEE) on 04-11-2016 As decided an inspection was conducted by DPCC Officials on 23.09.2016 and following observations were made: -STP (15 KLD) was installed and was also found operational condition. - Three DG Sets were installed with proper acoustic enclosure and adequate stack height. -Channelization done in kitchen and proper stack. -Treated wastewater being used in horticulture purposes. -Source of water is DJB and borewell (2 no) and outside tanker.	04-11-2016 Consent to Establish and Consent to Operate be granted.