



DELHI POLLUTION CONTROL COMMITTEE
DEPARTMENT OF ENVIRONMENT
(GOVT. OF NCT OF DELHI)
3rd FLOOR, BLOCK-I, DMRC IT PARK BUILDING,
SHASTRI PARK, DELHI-53
 (visit us at website : <http://dpcc.delhigovt.nic.in/>)



DPCC/(10)(02)(03)/Leg-25 /5298-5301

Date: 28/03/2025

To,

District Magistrate (South-West),
Old terminal Tax building,
Kapashera,
New Delhi-110037.

Subject- Illegal Borewell in M/s Krishna Farm House, KH No. 12/27. MIN.0-16 12-27 MIN 11-16. 13-26. 0-6. 28 1-15 12-28. 6-10. 26. 5-6. Kapashera, Delhi – 110037.

Sir,

This refers to the inspection of, M/s Krishna Farm House, KH No. 12/27. MIN.0-16 12-27 MIN 11-16. 13-26. 0-6. 28 1-15 12-28. 6-10. 26. 5-6. Kapashera, Delhi – 110037 by the officials of DPCC on 18.3.2025. During the inspection, one borewell was found being used for extracting the ground water without requisite permission from the Competent Authority.

In view of the above, you are kindly requested to look into the matter and direct the concerned to check legality of the borewell and take necessary action for sealing the same if found illegal. An action taken report may kindly be sent to this office. An early action in this regard is highly appreciated.

Incharge, CMC-II
Email ID: bmsreddy.dpcc@delhi.gov.in

Dr. B.M.S. Reddy
Senior Environmental Engineer
Delhi Pollution Control Committee
4th & 5th Floor, ISBT Building,
Kashmere Gate, Delhi, Delhi-110006

Copy to:-

1. Executive Engineer (SW)-II, Delhi Jal Board, NCT of Delhi, Room No-101, 1st Floor, Over Head Tank, Najafgarh, New Delhi-110043.
2. M/s Krishna Farm House, KH No. 12/27. MIN.0-16 12-27 MIN 11-16. 13-26. 0-6. 28 1-15 12-28. 6-10. 26. 5-6. Kapashera, Delhi – 110037
3. Master File, CMC-II.